

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7225)

-----  
Set quarter sec. post, from which a  
Red Fir 14" dia., bears N.80°E., 13 lks. dist.  
Cedar 5" dia., bears S.45°W., 16 lks. dist.

L.G. Hicks - For: Rice Bros - May 1916 (added 8/17/2009) - M13-72 & C.S. File 19/28

-----  
3" Cedar stake  
Red Fir 14" N.80°E., 8.6  
Cedar 5" S.45°W., 10.6

John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: George Vaughn - July 16, 1951 - C.S. File 40/277-8

-----  
Found - A dead Cedar snag on the ground bears S.45°W., 10.6 ft. scribed ¼ S BT.  
A Fir 20" dia., bears N.80°E., 8.6 ft., O.B.T.  
At corner point found old burnt post scribed.  
(See M 13-72 for Hicks corner.)  
I set 1" x 30" Iron pipe, from which  
A 34" Fir bears N.47°E., 14.0 ft. mkd. ¼ S S5 BT.  
A 17" Laurel bears S.59°E., 61.0 ft. mkd. ¼S S8 T30S R6W 2880 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman - Jan/Feb. 1964 - C.S. File 53/40-24

-----  
Found - 1" I.P. at corner and both BTs as recorded by Markham.  
17" Laurel S.59°E., 61.0 ft. bark scribed. We wood scribe "¼ S8 CS BT".  
Road bears North, 35 ft.

BLM resurvey by Jelley & Rogers under Group #s 1024 & 1039, Survey Apr/Oct, 1980 (DCSO recs. Vol. 42 Pgs 16568-69)

-----  
The 1/4 sec. cor. perpetuated and recorded by L.G. Hicks in 1910, further perpetuated and recorded by Markham in 1951, monumented with an I.P. 1¼" dia., firmly set, projecting 12" above ground from which the remains of the original bearing tree:

A sawed Fir stump 25" dia., bears N.80°E., 13 lks. dist., (to face) with axe marks in bark.  
and the remains of bearing trees mkd. by Markham:  
(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed Fir stump 33" dia., bears N.51°E., 24 lks. dist., with scribe marks ¼ S5 visible on bark.

A sawed Madrone stump 20" dia., bears S.58°E., 88 lks. dist., with scribe marks ¼ S8 CS BT visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, directly over iron pipe, with brass cap mkd:

T 30 S R 6 W

1/4  $\frac{S\ 5}{S\ 8}$

1980

from which new bearing trees:

A Fir 9" dia., bears N.58 ¾°E., 7 lks. dist, mkd. ¼ S5 BT.

A Fir 8" dia., bears S.73½°W., 115 lks. dist, mkd. ¼ S8 BT.

Greg Lang - For: Rick Barnes - July 2005 - M148-10 & C.S. File 65/54-26B

-----  
Found - Brass Cap set by BLM  
Existing 14" Fir bears S.82¼°W., 4.70 ft (1980 BLM)  
Existing 16½" Fir bears N.58¾°E. 75.60 ft (1980 BLM)  
Note - It appears that the distances to the two trees above were switched when compared to those given on BLM notes.  
New - A 11½" Fir bears N.85¾°E. 32.80 ft scribed "¼ S5 BT"  
A 15" Fir bears N.26¼°W., 39.40 ft scribed "¼ S5 BT"  
Note - We set spikes in the base of all existing & new BTs for measuring distances to the corner; bearings to the trees were measured with a total station & are based on the 1965 & 1982 BLM plats.  
Corner lies on the southerly side of an existing rd.

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0906, surveyed June/July 2009 - (DCS0 recs Vol. 56 Pg 22318 & Plat T30-6 2011)

-----  
The ¼ sec. cor. of secs. 5 & 8, monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground with brass cap (properly) mkd.

from which the remains of an orig. BT

A sawed, decayed fir stump, 24" dia., bears N.80°E., 8.6 ft. with no marks visible.

and the remains of BTs mkd. by Markham in 1951, reported by Jelley & Rogers

A sawed fir stump, 31" dia., bears N.51°E., 15.8 ft., with no marks visible and a galvanized metal cover. Cont.

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed madrone stump, 23" dia., bears S.58°E., 58.1 ft. with fragmentary scribe marks visible on an opened blaze.  
and BTs mkd by Jelley and Rogers  
A fir, 18" dia., bears N.58¾°E., 75.9 ft. with a healed blaze. (Rec. 4.6 ft.)  
A fir, 14" dia., bears S.73½°W., 4.6 ft. with a healed blaze (rec. 75.9 ft.)  
and BTs mkd. by Lang in 2005  
A fir, 12" dia., bears N.85¾°E., 32.8 ft. with fragmentary scribe marks visible on a partially healed blaze.  
A fir 16" dia., bears N.26½°W., 39.4 ft. with fragmentary scribe marks visible on a partially healed blaze.  
Corner is located 35.0 ft. S of a graveled road, 12 ft. wide, bears N.60°E., and S.65°W.