

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec Cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7217)

-----  
Set post, cor. to secs. 8, 9, 16 and 17, from which  
A Cedar 15" dia., bears S.35°W., 206 lks. dist.  
A Pine 15" dia., bears S.40°E., 92 lks. dist.  
A Fir 36" dia., bears N.80°W., 19 lks. dist.  
A Fir 20" dia., bears N.45°E., 133 lks. dist.

Douglas Co. Surveyors Office - Arthur Boyer, DCS - Wit: Geo. Piper; Hilton Fogus; Al Weekley - Jan. 13, 1943 - C.S. File 31/9

-----  
The original BTs for this corner were found but not the 40" Fir recorded as N.80°W., 19 lks. For this tree: marked a 40" Fir N.8°W., 12½ ft. and scribed it.  
The 40" Cedar S.35°W., 206 lks. actually is S.35°W., 118 ft. - rescribed it.  
The 18" Pine S.40°E., is as given or 61 ft. = 92 lks.  
The 40" Fir shows as N.45°E., 133 lks. is 93.0 ft. rescribed on bark.

John H. Markham, Jr. - For: Hanna Coal & Ore Co. - June/July 1957 - C.S. File 42/273-3

-----  
Location of corner determined by O.B.T.s:  
40" Fir snag bears N.40°W., 11.0 ft., found scribe.  
44" Cedar S.33°W., 118.0 ft., found scribe.  
22" Pine S.34°E., 62.0 ft., found scribe.  
45" Fir N.35°E., 90.0 ft., found scribe.  
At corner point, found 6" x 6" scribed post in large mound of stone. I set an I.Pipe with brass cap in concrete mkd: T30S R6W 8-9-16-17, 2880, 1957, from which:  
13" Fir bears N.57°E., 48.3 ft. mkd. S9 BT.  
9" Fir bears S.12°E., 37.1 ft. mkd. S16 BT.  
15" Fir bears S.46°W., 41.4 ft. mkd. S17 BT.  
6" Fir bears N.73°W., 33.2 ft. mkd. S8 BT.

Fd. 0k 7/1964 DCSO C.S. File 53/40-60