

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION N. Sec. Cor. for 4 & 5 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6459)

-----  
Set a post, at proper distance, cor. of secs. 4, 5, 32 and 33, from which

- A R.Fir 24" dia., bears S.35°W., 11 lks.
- A R.Fir 30" dia., bears S.65°E., 44 lks.
- A R.Fir 20" dia., bears N.50°E., 41 lks.
- A R.Fir 30" dia., bears N.5°W., 83 lks.

Reestablished corners by Fred Mensch, 1905, under Contract #757 (DCSO records, Vol. 15 Page 6502)

-----  
The corner being partially obliterated, I re-establish this corner in its original position, as follows:

Set a limestone 18x10x10 ins. 12" in the ground for cor. of secs. 4 and 5, mkd. with 4 notches on E. and 2 notches on W. edge, from which

- A R.Fir 36" dia., bears S.66°E., 43 lks. mkd. T30S R6W S4 BT.
- A R.Fir 30" dia., bears S.7°W., 25 lks. dist., mkd. T30S R6W S5 BT.

BLM resurvey by Thielsen and White, under Group #'s 1024 and 1039. Surveyed July 1958/Aug. 1959 (DCSO records, Vol. 30 Page 12811)

-----  
The cor. of secs. 4 and 5, determined at record bearing and distance from trees mkd. by Mensch in 1904

- A Fir 44" dia., bears S.66°E., 43 lks. dist., mkd. with a burned blaze.
- A Fir snag 36" dia., bears S.7°W. 25 lks. dist., mkd. with a burned blaze.

At the Corner Point

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd:

T 29 S  
S 32  
S 5 | S 4  
T 30 S R 6 W  
1958

from which new bearing trees

- A Cedar 18" dia., bears S.16¼°E., 108 lks. dist., mkd. T30S R6W S4 BT.
- A Fir 43" dia., bears S.39½°W., 94 lks. dist., mkd. T30S R6W S5 BT.

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION N. Sec. Cor. for 4 & 5 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Doug. County Surveyors Office - Gary Langlitz, Deputy - Peter Earle - Feb. 21, 1974 - C.S. File 56/43-19

-----  
Found - 1958 Cadastral brass cap, properly mkd. laying on the ground. I reset same brass cap in its original position, from which:  
44" D.Fir bears S.66°E., 28.4 ft. with a burned blaze, previously opened.  
36" D.Fir snag, bears S.7°W., 16.5 ft. with a burned blaze, previously opened.  
18" now 20" R.Cedar bears S.16¼°E., 71.3 ft. scribing T30S R6W S4 BT plainly visible.  
43" D.Fir now a stump bears S.39½°W., 62.0 ft.  
New BT - 12" Grand Fir bears N.48°W., 35.2 ft. scribed T29S R6W S32 CS BT.

Note: Upon resetting brass cap, I find a 1½" truck axle with 8" dia. wheel bolt flange attached, driven flush with the ground, bearing North 0.8 ft. from the corner point. Corner lies approx. 80 ft. West of a dirt road.

BLM resurvey by Jelley and Rogers, under Group #'s 1024 and 1039. Surveyed April/Oct. 1980 (DCSO rec Vol. 42 Pg 16563)

-----  
The sec. cor., monumented with an I.Post 2½" dia., firmly set, projecting 4" above ground, with 1958 brass cap, from which the remains of bearing trees mkd. by Mensch:

A sawed Fir stump 44" dia., bears S.66°E., 43 lks. with burned blaze.

A Fir snag 36" dia. bears S.7°W. 25 lks. with burned blaze and the remains of bearing trees mkd. by Thielsen and White

A sawed Cedar stump 20" dia., bears S.16¼°E., 108 lks., with illegible scribe marks visible on partially healed blaze.

A sawed Fir stump 45" dia., bears S.39½°W., 94 lks. with illegible scribe mks visible on partially healed blaze and a bearing tree mkd. by Langlitz, in 1974

A Fir 13" dia., bears N.48°W., 52½ lks. with healed blaze. and new bearing trees

A Fir 5" dia., bears S.18°E., 52 lks. mkd. T30S R6W S4 BT.

A Fir 6" dia., bears S.47°W., 28 lks. mkd. T30S R6W S5 BT.

DCSO-GIS Corner visitation - 8/11/2004 - Typed: 2/9/2011 - C.S. File 67/33-1

-----  
Monument - 3" Comment - Ok

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION N. Sec. Cor. for 4 & 5 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0906, surveyed June/July 2009 - (DCS0 recs Vol. 56 Pg 22317 & Plat T30-6 2011)

-----  
The cor. of secs. 4 & 5 only, on the N bdy of the Tp. monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd from which the remains of BTs mkd by Mensch, reported by Jelley & Rogers

A sawed fir stump, 42" dia., bears S.66°E., 28.4 ft. with fragmentary scribe marks visible on an opened blaze.

A decayed fir snag, 36" dia., bears S.7°W., 16.5 ft. with no marks visible.

and the remains of BTs mkd. by Thielsen & White, reported by Jelley & Rogers

A sawed cedar stump, 20" dia., bears S.16¼°E., 71.3 ft. with scribe marks 30 S R8W S4 visible on a partially healed blaze.

A sawed decayed fir stump, 46" dia., bears S.39½°W., 62.0 ft. with no marks visible.

and a BT mkd by Langlitz in 1974, reported by Jelley & Rogers

A fir, 23" dia., bears N.48°W., 34.7 ft. with a healed double blaze.

and the remains of BTs mkd by Jelley & Rogers

A fir snag, 13" dia., bears S.18°E., 34.3 ft. with a healed blaze.

A fir, 11" dia., bears S.47°W., 18.5 ft. with a healed blaze.

and a new BT

A fir, 15" dia. bears S.34°E., 49.4 ft mkd: T30S R6W S4 BT  
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Fd. BC & 4 BTs by D. Edwards, 3/2011 - M162-22