

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7212)

Set quarter sec. post from which  
Red Fir 8" dia., bears S.60°W., 25 lks. dist.  
Pine 24" dia., bears N.40°E., 55 lks. dist.

BLM Resurvey by Lynn Roseberry, under Group #649, Survey Aug/Sept. 1967 (DCSO records, Vol 35 Pg. 14344)

The ¼ sec. cor. of secs. 9 and 10, determined at record bearing and distance from the original bearing trees:

A sawed and burned pine stump 35" dia., bears N.40°E., 55 lks., with no marks remaining.

A sawed and burned fir stump 32" dia., bears S.60°W., 25 lks., with no marks remaining.

and a locally established BT of which I have no record:

A Fir snag 20" dia., bears S.27°W., 59 lks., with scribe marks ¼ S BT visible on open double blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:

¼  
S 9 | S 10  
T 30 S R 6 W  
1967

from which new bearing trees:

A Fir 15" dia., bears S.40°E., 161 lks., mkd. ¼ S10 BT.

A W. Fir 10" dia., bears S.73°W., 475 lks. mkd. ¼ S9 BT.

The corner falls at the NW. cor. of timber, edge bears E & S.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 3/22/2011 - C.S. File 67/33-24

Found - 3½" dia., (1967) brass cap (properly marked) on a 2½" O.D. iron pipe is firmly set and protrudes 9" above ground. Monument is set on NE edge of fence corner post with fences running north & east.

A R. Fir 8" dia., now a 3 ft. tall, 32" dia., rotted fir stump with no remaining markings; bears S.60°W., 17.0 ft. (rec. S.60°W., 16.5 ft. is a good face measurement) Orig.

A Pine 24" dia., now a 2 ft. tall, approx. 16" dia., rotted pine stump with no remaining markings; bears N.38°E., 37.3 ft. (rec. N.40°E., 36.3 ft. is a good face measurement) Orig.

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A fir snag 20" dia., now 1½ ft. tall approx. 12+ inch dia., very rotted fir stump with no remaining marks bears S.27°W., 37.9 ft. (rec. S.27°W., 38.9 ft.) No record of this BT

A fir 15" dia., now a 25" DBH D.Fir with a fully healed single blaze; bears S.41½°E., 106.3 ft. (rec. S.40°E., 106.3 ft.) 1967

A W.Fir 10" dia., now a 24" DBH G.Fir (lowland W.Fir) with a fully healed single blaze; bears S.73°W., 313.5 ft. (as per record) 1967

New - A 14" DBH I.Cedar scribed "¼ S10 CS" "BT" on a double blaze; bears N.53½°E., 53.2 ft.

A 19" DBH D.Fir (which is double trunked above 12 ft.) scribed "¼ S9 CS" "BT" on a double blaze; bears N.28½°W., 21.3 ft.

Note - Corner is located on very gentle SW slope in old reprod. Mixed forest of fir, cedar Madrone & pine.  
Compass decl. 15¾°E.