

PRIMARY CORNER DESCRIPTION Sec. Cor for 2, 3, 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page 7207)

Set post, cor. to secs. 2, 3, 10 and 11, from which
Laurel 18" dia., bears S.20°E., 19 lks. dist.
B.Oak 18" dia., bears N.47°E., 27 lks. dist.
Red Fir 20" dia., bears N.80°W., 29 lks. dist.
Laurel 15" dia., bears S.50°W., 28 lks. dist.

John H. Markham, Jr. - For: Stomar Lumber - June 26, 1957 - C.S. File 42/274

Location of corner determined by O.B.T.s.
A 50" Fir bears N.67°W., 19.2 ft.
A 20" Laurel bears S.15°E., 14.2 ft. (I rescribed S11 T30S R6W BT)
At corner point found 4" x 4" wood post and Set 2½" x 24" Iron pipe from which
30" Laurel bears N.6°E., 36.3 ft. mkd. S2 T30S R6W BT.
18" Laurel bears N.61°30'W., 55.2 ft. mkd. S3 T30S R6W BT.
22" Laurel bears S.76°W., 58.0 ft. mkd. S10 T30S R6W BT.
25" B.Oak bears S.10°E., 88.2 ft. mkd. S11 T30S R6W BT.
A fence bears South 154.0 ft. at edge of large opening - fence runs NW and SE.
Corner lies on top of main ridge.

Found OK, Herbert Northcraft, 1974 - M 54-13

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1551, Surveyed Aug/ 1990/July 1991 - (DCSO records Vol. 50 Page(s) 19206)

The cor. of secs. 2, 3, 10, and 11, perpetuated by John H. Markham, Jr., in 1957, monumented with an iron pipe, 24 ins. long, 2½ ins. diam., firmly set, projecting 8 ins. above ground, from which the remaining original bearing trees:
A madrone, 35 ins. diam., bears S. 15° E., 19 lks. dist., with healed blaze. (Record, S. 20° E.)
A fir, 55 ins. diam., bears N. 57° W., 29 lks. dist., with healed blaze. (Record, N. 80° W.)
and the remains of bearing trees mkd. by Markham
A madrone, 32 ins. diam., bears N. 16° E., 54 lks. dist., with healed blaze.
A black oak, 32 ins. diam., bears S. 10° E., 130 lks. dist., with healed blaze.

(Cont. Next Page)

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole, bears S. 86° W., 87 lks. dist., with a down
madrone alongside, 30 ins. diam., with illegible scribe
marks visible on partially healed blaze.

A madrone, 24 ins. diam., bears N. 50° W., 84½ lks. dist.,
with scribe marks R6 S2 visible on partially healed
blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
22 ins. in the ground, with brass cap mkd.

T30S	R6W
<u>S3</u>	<u>S2</u>
S10	S11
1990	

from which a new bearing tree

A fir, 7 ins. diam., bears S. 23° W., 109 lks. dist., mkd.
T30S R6W S10 BT.

Deposit a white "DEEP-1" magnetic marker at the base and the
iron pipe alongside the stainless steel post.

The corner is located at the corner of fences, extending E.,
W., and S.

From this point, the Bureau of Land Management Geodetic
Control Station No. EC 41056, at latitude 42° 58' 53.756" N.,
longitude 123° 23' 16.850" W. (NAD 1927), determined by the
NAVSTAR Global Positioning System, bears S. 32° 11' 00" W.,
23.018 chs. dist. (mean bearing and sea level distance),
monumented with an aluminum tablet, 3 ins. diam., set in
cement flush with the ground, mkd. EC 41056 GPS 1990.