

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by - Addison R. Flint, Deputy Surveyor, Under Contract #56, dated 1855 (DCSO records Vol. 17 Page(s) 7203)

Set quarter sec. post from which a
W. Oak 6" dia., bears S.10°E., 6 lks. dist.
Laurel 7" dia., bears S.75°W., 25 lks. dist.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1551, Surveyed Aug/ 1990/July 1991 - (DCSO records Vol. 50 Page(s) 19202)

The ¼ sec. cor. of secs. 1 and 2, determined at record bearing and distance from the remains of the original bearing trees:

A decayed oak snag, 14 ins. diam., bears S. 10° E., 6 lks. dist., with rotted out upper blaze and scribe mark B in reverse visible on overgrowth removed from rotted lower blaze.

A madrone, 16 ins. diam., bears S. 75° W., 25 lks. dist., no marks remaining on rotted out blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T30S R6W

¼

S2 S1

1991

from which new bearing trees

A fir, 22 ins. diam., bears N. 39¼° E., 59 lks. dist., mkd. ¼ S1 BT.

A fir, 26 ins. diam., bears N. 39½° W., 29 lks. dist., mkd. ¼ S2 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.