

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 918030

PRIMARY CORNER DESCRIPTION Cor. #3 M.S. #186

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Survey by W.F. Briggs, U.S. Deputy Mineral Surveyor - For:
Edson Adams and Harvey Brown, Emerald Lode Claim - Survey,
Nov. 9, 1888 (DCSO records Vol. 28 Page(s) 11839)

Set post, 4 ft.long, 3" sq., 18" in the ground, with stone
mound alongside, mkd. E.M.C. Cor No 3; from which
A Pine 16" dia., bears S.42½°W., 21 ft. dist., mkd. E.M.C.
Cor No 3 BT.
A Pine 12" dia., bears N.8½°W., 59 ft. dist., mkd. E.M.C.
Cor No 3 BT.

John H. Markham, Jr. For: Hanna Coal & Ore Co. - Wit: E.D.
Jenks; G.D. Myers - Aug/Sept. 1957 - C.S. File 42/288-4

Emerald Lode Claim Cor. #3 Sec. 18, as det. by O.B.Ts
30" Pine bears S.42½°W., 21.0 ft., found scribe.
22" Pine snag bears N.8°30'W, 59 ft.
At corner point Set brass cap in concrete mkd. E.M.C. #3 T30S
R6W 2880 1957, from which
30" Pine bears S.63°W., 72.2 ft. mkd. E.M.C. 3 BT.
20" Cedar bears N.56°E., 114.2 ft. mkd. E.M.C. 3 BT.
Main mine road bears East, 40 ft.