

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7274)

Set an Oak post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. marked 1/4 S. on N. face, from which
A Pine 48" dia., bears N.10°E., 180 lks. dist. mkd. 1/4 S BT
A Live Oak 7" dia., bears S.52°E., 180 lks. dist. mkd. 1/4 S BT.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7296-97) and duplicated info. in Vol. 27 Pg. 11618)

The point for old 1/4 sec. cor., located by reference to the bearing trees. At the exact cor. point
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap mkd: 1/4 $\frac{S\ 30}{S\ 31}$
from which 1918
A Yellow Pine 50" dia., bears N.10°E., 180 lks. dist. mkd. 1/4 S30 BT. (Old BT)
A Live Oak 18" dia., bears S.54°E., 178 lks. dist. mkd. 1/4 S31 BT. (Old BT)

Douglas Co. Surveyors Office - Vernon R. Tracy; Mike Darby; Terry Connell, crew - July 1965 - C.S. File 53/40-82

Found - 1918 GLO brass cap at corner.
Orig. 50" now 56" Y.Pine N.10°E., 118.8 ft., unhealed scar shows "1/4 S30 BT", tree appears to be dying.
Orig. 18" now 23" Live Oak S.54°E., 117.5 ft., shows good scar.
Due to Pine tree condition and dense brush, we mark new BTs:
11" D.Fir S.11°E., 11.4 ft. mkd. 1/4 S31 CS BT.
14" Y.Pine N.17°W., 10.3 ft. mkd. 1/4 S30 CS BT.
This corner lies on East slope of rolling bench approx. 100.0 ft. West of small, dry creek bed.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - July 26, 1984 - M 97-28

Found - 1918 GLO brass cap and iron pipe.
50" Pine N.10°E., 118.8 ft., staub with vis. scribe.
14" Pine N.17°W., 10.3 ft., scribe visible.
11" Fir S.11°E., 11.4 ft., snag.
New BT - 10" Fir S.20°W., 30.3 ft.

cont.

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Quimby - Crew: J. Leonard - 10/2017 - C.S. File 65/99-16

Found - 1918 GLO brass cap on 1" IP (properly mkd)
4 burned out root holes.

Set - I.Rods with yellow plastic cap, cap stamped ie
engineering, with 5' alum. cap alongside I. Rods:
N.42°W 12.9
S.35°E., 21.1
N.39°E., 22.1
S.39°W., 21.6

Note - Area badly burnt 9/2017
Dec. 15½°E.