

PRIMARY CORNER DESCRIPTION Sec Cor for 29, 30, 31 and 32

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7272)

 (along S. slope of mt., very rocky and broken)
 Set a stone 16 x 12 x 6 ins., 10" in the ground for the cor. to secs. 29, 30, 31 and 32, marked with 1 notch on the S. and 5 notches on the E. edges, from which
 Live Oak 6" dia., bears N.60°E., 17 lks. dist. mkd. T30S R7W S29 BT.
 Live Oak 6" dia., bears S.59°E., 26 lks. dist., mkd. T30S R7W S32 BT.
 Laurel 6" dia., bears S.12°W., 87 lks. dist., mkd. T30S R7W S31 BT.
 Live Oak 5" dia., bears N.74°W., 20 lks. dist., mkd. T30S R7W S30 BT.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7297) and duplicated info. in Vol. 27 pgs. 11618-19)

 The old sec. cor., which is a stone, firmly set, witnessed by the SW. bearing tree, which is dead. Alongside the old cor. Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 29, 30, 31 and 32, with brass cap marked:

T30S	R7W
<u>S30</u>	<u>S29</u>
S31	S32
1918	

from which
 A Fir 12" dia., bears N.85°30'E., 75 lks. dist. mkd. T30S R7W S29 BT.
 A Fir 16" dia., bears S.77°30'E., 44 lks. dist. mkd. T30S R7W S32 BT.
 A Yellow Pine 14" dia., bears S.59°30'W., 83 lks. dist. mkd. T30S R7W S31 BT.
 A Cedar 9" dia., bears N.83°W., 181 lks. dist. mkd. T30S R7W S30 BT.

Fd ok by DCSO Nov. 1969: Fd. 1918 GLO Brass cap & BTs in good cond. - We tag BTs & put location mkr's on 4" DF 6" E of brass cap. (Info added 3/13/2019 DCSO JC) C.S. 53/40-95