

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7275-76)

Set stone 12x9x7 ins., 8" in the ground for ¼ sec. cor. marked ¼ on W. face, and from which
A Fir 24" dia., bears N.84°E., 68 lks. dist., marked ¼ S BT.
A Cedar 4" dia., bears S.70°W., 13 lks. dist. marked ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman crew - Feb. 1964 - C.S. File 53/40-46

Found - Orig. 24" now 30" R.Fir N.84°E., 44.9 ft., shows faint scribe.
Corner stone and SW. BT not found.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W
¼ S30 | S29
1964
New BTs -20" Pine bears S.18°E., 19.0 ft. scribed ¼ S29 CS BT.
12" R.Fir bears S.42½°W., 29.2 ft. scribed ¼ S30 CS BT.
Corner is on steep 1:1 rocky slope.

Cor. Fd. and used in BLM resurvey by Stephen D. Albright and Jack W. Bowder, Cadastral Surveyors, under Group #787, surveyed July/Aug. 1972 - (DCSO records Vol. 36 Page(s) 14886-87)