

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7272)

Set a Fir post, 3 ft. high, 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S on N.face, from which
A Pine 24" dia., bears S.20°W., 25 lks. dist. mkd. ¼ S BT.
A Fir 14" dia., bears N.54°E., 22 lks. dist. mkd. ¼ S BT.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7301-02) and duplicated info. in Vol. 27 Pg. 11622)

The old ¼ sec.cor., located by reference to the bearing trees. At the exact cor. point
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. with brass cap marked: ¼ $\frac{S\ 29}{S\ 32}$
1918

from which
A Fir 18" dia., bears N.54°E., 23 lks. dist. mkd. ¼ S29 BT. (Old BT)
A Yellow Pine 30" dia., bears S.19°W., 26 lks. dist. mkd. ¼ S32 BT. (Old BT)

Survey by Howard Johnstone, LS #498 - For: Roseburg Lumber Co. - Sept. 24, 1984 - M 97-50

Found - 1918 GLO brass cap and iron pipe.
23" Fir, tall stump, N.54°E., 15.2 ft., healed.
30" Pine snag, S.19°W., 17.2 ft., scribe visible.
New BT - 8" Cedar S.64°W., 30.5 ft.

Ron Quimby - Crew: R. Olsen & J. Leonard - 10/2017 - C.S. File 65/99-21

Found - 1918 brass cap on 1" I.Pipe (properly mkd)
Fir stump N.54°E., 15.2 ft. badly burnt.
Root hole S.19°W., 17.2
9" cedar S.64°W., 30.5 ft. good scar.
New - 2.5x3.0 flat top stone 1 ft above ground with X & PK
N.54°E., 44.5 ft. with post alongside.
9" fir S.43°E., 56.6 ft. scribed ¼ S32 BT.
50" Fir N.40°W., 32.4 ft. bark scribed ¼ S29 BT.
30" Fir S.60°W., 42.1 ft. scribed ¼ S32 BT.
Note - Area badly burnt 9/2017
Dec. 15½°E.