

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7263)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. marked 1/4 S on W. face from which

A Laurel 20" dia., bears N.46°W., 25 lks. dist. mkd. 1/4 S BT.

A Laurel 12" dia., bears S.65°E., 34 lks. dist. mkd. 1/4 S BT.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7304) and duplicated info. in Vol. 27 Pgs. 11623-24)

The old 1/4 sec. cor. located by reference to the bearing trees. The SW. tree is down. At the exact cor. point

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap mkd:

1/4
S32 | S33
1918

from which

A W.Fir 30" dia., bears N.29°E., 14 lks. dist. marked 1/4 S33 BT. (Old BT)

A W.Fir 24" dia., bears S.61°W., 30 lks. dist. marked 1/4 S32 BT. (New BT)

Cor. reported as Fd. OK by Floyd White of Roseburg Lumber Co. - Report filed March 1965, in C.S. File 53/40-98

Fd. OK, Sept. 1984 by H. Johnstone - M 97-50

Mark Smalley - For: Roseburg Resources Co. - January 2000 - M 134-7

Found - 1918 GLO brass cap on iron pipe.
38" Fir N.29°E., 9.2 ft. healed.

24" rotten staub S.61°W., 20.0 ft.
New BTs- 16" W.Fir N.14°W., 26.0 ft. "1/4 S BT"
9" W.Fir S.2°W., 30.6 ft. "1/4 S BT"
9" W.Fir S.67°E., 45.9 ft. "1/4 S BT"

Ron Quimby - Crew: R. Olsen & J. Leonard - 9/2017 - C.S. File 65/99-2

Condition report only

Found - 1918 GLO brass cap on 1" Iron pipe (properly mkd)
42" Fir N.29°E., 9.2 ft. good scar.
26" W.Fir N.14°W., 26.0 ft. good scar. cont. next pg

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

14" W.Fir S.2°W., 30.6 ft. good scar.
24" stub now burnt out hole S.61°W., 20.0 ft.
Note - Corner is n SW corner of clearcut unit. Area is
badly burnt 8/2017
Compass decl. 15½°E.