

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7265-66)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground for the cor. to secs. 16, 17, 20 and 21, marked T30S R7W S16 on NE.; S21 on SE.; S20 on SW.; S17 on NW. faces, with 3 notches on S. and 4 notches on E. edges, from which

A Laurel 7" dia., bears N.78°E., 11 lks. dist. mkd. T30S R7W S16 BT.

A Laurel 7" dia., bears S.14°E., 23 lks. dist. mkd. T30S R7W S21 BT.

A Laurel 18" dia., bears S.41°W., 10 lks. dist. mkd. T30S R7W S21 BT.

A Fir 15" dia., bears N.10°W., 45 lks. dist. mkd. T30S R7W S17 BT.

Douglas Co. Surveyors Office - Vernon R. Tracy, M. Darby and J. Barnett, crew - May 20, 1965 - C.S. File 53/40-71

Found - Orig. 7" now 8" Laurel N.78°E., 7.3 ft., down and out of place, shows "S" and parts of other letters in reverse scribe, badly rotted.

Orig. 7" now 8" Laurel S.14°E., 15.2 ft., shows parts of reverse scribe, also down and rotted.

Orig. 15" now 30" Fir N.10°W., 29.7 ft., shows fair bark scribe "T30S R7W S17 BT", alive and in good condition.

No trace of other BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 7 W

S 17 | S 16

S 20 | S 21

1965

New BTs -13" D.Fir S.37°E., 12.8 ft. mkd. T30S R7W S21 CSBT

12" D.Fir N.64°E., 11.0 ft. mkd. T30S R7W S16 CSBT

7" D.Fir N.39°W., 30.0 ft. mkd. T30S R7W S17 CS BT

14" D.Fir S.81°W., 27.0 ft. mkd. T30S R7W S20 CSBT

Cor. Fd. and used in BLM resurvey by Albright and Bowder, Cadastral Surveyors, under Group #787, surveyed July/Aug. 1972 - (DCSO records, Vol. 36 Pg. 14893)

Survey by Howard W. Johnstone - For: Roseburg Lumber Co. - June 11, 1984 - C.S. File 58/296

Found - 34" D.Fir N.10°W., 29.5 ft., now a stump. (OBT)
(Cont. Next Page)

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

12" D.Fir N.64°E., 11.0 ft., now a stump.
16" D.Fir S.37°E., 12.8 ft., stump hole.
10" D.Fir N.39°W., 30.0 ft., stump.
17" D.Fir S.81°W., 27.0 ft., stump with part of scribe visible.
All stumps painted yellow and tagged with yellow location marker tags. Brass cap not found, recent logging has destroyed this corner and BTs.
Set 48" x 5/8" Iron rod with alum. cap marked "T30S R7W 1984 16 17 20 21 RLS 498".
New BT - 29" D.Fir S.18°E., 29.5 ft.
No other trees within a reasonable distance.

Howard Johnstone - For: Roseburg Lumber Co. - June 11, 1984 - C.S. File 58/296-6

Bearing tree added to corner:
8" D.Fir N.43°W., 277.5 ft. (No other trees closer in section 20).
Corner about 200 ft. East of road. Section 16 and 20, clearcut.

Greg Lang - June 2013 - C.S. File 65/78-54

Found - 5/8" iron rod & alum. cap set by Johnstone in 1984.
Fir stump (record N.64°E., 11.0')
Fir stump (record S.81°W., 27.0')
Now 14" D.Fir (record N.43°W., 277.5')
D.Fir S.18½°E., 29.5'
New BTs- 7" D.Fir bears S.80¼°W., 9.50' scribed "S20 BT"
9" D.Fir bears N.25¼°W., 22.90' scribed "S17 BT"
6" D.Fir bears N.17¼°E., 11.40' scribed "S16 BT"
Note - Bearings are to the center of the trees & distances are measured to a spike in side of the trees.
Corner lies 300' +/- easterly of a sharp left corner in dirt road on an easterly slope.

2