

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7265)

Set a Laurel post 3 ft. long 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S. on N. face, from which
A Laurel 7" dia., bears S.20°W., 5 lks. dist. mkd. ¼ S BT
A Laurel 8" dia., bears N.25°E., 14 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Vernon Tracy, M. Darby and J. Barnett, crew - April 28, 1965 - C.S. File 53/40-67

Found - Orig. 7" now 7" Laurel, down and badly rotted, S.20°W., 3.3 ft. Find old face, scribe rotted away.
Orig. 8" now 9" Laurel, N.25°E., 9.2 ft., down and upper face rotted badly, find "B" scribe on lower face in poor condition.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W
¼ S 21
S 28
1965

New BTs -22" D.Fir S.34°W., 9.4 ft. mkd. ¼ S28 CS BT.
24" D.Fir N.55°E., 6.6 ft. mkd. ¼ S21 CS BT.
This corner lies on side hill sloping S.16°E.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #571, surveyed May/June 1965 - (DCSO records Vol. 33 Page(s) 13870)

The ¼ sec. cor. perpetuated by the DCSO in 1965, monumented with an iron post, 1" dia., firmly set, extending 6" above the ground, with properly mkd. brass cap from which the original bearing trees:

A down and rotted Madrone, 9" dia., bears N.25°E., 14 lks. dist. with fragmentary scribe marks visible on rotted double blaze.

A down and rotted Madrone 7" dia., bears S.20°W., 5 lks. dist. no marks remaining.

and County Surveyor's bearing trees:

A Fir 25" dia., bears N.55°E., 10 lks. dist. mkd. ¼ S21 CS BT on double blaze.

A Fir 23" dia., bears S.34°W., 14 lks. dist. mkd. ¼ S28 CS BT on double blaze.

Add marks BLM 1965 to brass cap.

(Cont. Next Page)

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and used in BLM survey by Lance Bishop, Cadastral Surveyor, Group #1170, surveyed Sept. 1983 - (DCSO records, Vol. 47 Page 17839)

Fd. OK, April 1993 by M. Smalley - C.S. File 63/153-10