

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 450 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7260)

Set Cedar post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. marked 1/4 S. on N. face, from which

A Fir 36" dia., bears N.42°E., 25 lks. dist. mkd. 1/4 S BT

A Fir 16" dia., bears S.26°E., 51 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - Vernon Tracy and Mike Darby, crew - May/June 1965 - C.S. File 53/40-78

Found - Orig. 36" now 41" Fir N.42°E., 16.5 ft., shows "1/4 S B" bark scribe, alive and in good condition.

Orig. 16" Fir S.26°E., 33.7 ft., down and out of position, found old axe mark and fragmentary scribe of "B".

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 7 W

1/4 S 3

S 10

New BTs -10" Yew S.1°E., 23.2 ft. mkd. 1/4 S10 CS BT.

13" Hemlock N.23°E., 22.0 ft. mkd. 1/4 S3 CS BT.

This corner lies on flat on E. side of Thompson Creek approx. 30.0 ft. East of creek.

Cor. Fd. and used in BLM resurvey by James Jelley, under Group #880, surveyed Aug/Oct. 1975 - (DCSO records, Vol 38 Pgs. 15599-600)

Fd. OK, Oct. 1980 by H. Johnstone - M 86-3