

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7238)

Set post cor. to secs. 26, 27, 34 and 35, from which
A Live Oak 12" dia., bears N.72°E., 76 lks. dist.
A Laurel 10" dia., bears S.50°E., 142 lks. dist.
A Live Oak 16" dia., bears S.50°W., 35 lks. dist.
A Fir 12" dia., bears N.75°W., 23 lks. dist.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Dale McFarland; John Powell, crew - May 22, 1963 - C.S. File 49/139-101

Found - Orig. 12" now 24" R.Fir snag N.75°W., 15.2 ft., previously opened, shows scribing.
Stool of Live Oak, shows old scars, bears S.50°W., 18.0 ft., not 23.1 ft.
No trace of NE. or SE. bearing trees.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W
S 27 | S 26
S 34 | S 35
1963

New BTs - 11" R.Fir bears S.49°E., 87.5 ft., on slope, scribed T30S R7W S35 CS BT.
18" Live Oak bears S.66°W., 17.0 ft. scribed S34 CS BT.
8" Live Oak bears N.19°W., 54.5 ft. scribed S27 CS BT.

Corner is on steep rocky East slope and about 100 ft. East of top ridge.

Cor. Fd. and used in BLM resurvey by James E. Jelley, under Group #897, surveyed Sept. 1976/June 1977 - (DCSO records, Vol. 41 Page 16247) and Group #1007, surveyed Aug. 1980/march 1982 - (DCSO records, Vol. 43 Pg. 16792)

Fd. OK, March 1994 by R. Quimbly - M 119-21