

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7240)

-----  
Set ¼ sec. post, from which  
A Pine 8" dia., bears S.60°E., 17 lks. dist.  
A Pine 20" dia., bears N.22°W., 34 lks. dist.

Survey by Howard W. Johnstone - For: Roseburg Lumber Co. - Aug. 18, 1962 - C.S. File 51/163-11

-----  
Found 20" Pine, N.22°E., (Rec. N.22°W) 34 lks.  
Set 1" x 30" iron pipe.  
Scribed -15" D.Fir S.51½°W., 23.8 ft.  
14" D.Fir N.50°E., 58.0 ft.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1007, surveyed Aug. 1980/March 1982 - (DCSO records Vol. 43 Page(s) 16794-95)

-----  
The ¼ sec. cor., perpetuated and recorded by R.E. Ware in 1975, monumented with an iron pipe, 1¼" dia., firmly set, projecting 10" above ground, from which the remains of an original bearing tree:

A root hole bears N.22°W., 34 lks. dist., with a down Pine alongside, 20" dia., with scribe marks BT visible on decayed blaze.

and bearing trees mkd. by Ware:

A Fir 20" dia., bears N.52°E., 85 lks. dist., with healed double blaze.

A Fir 20" dia., bears S.52°W., 35½ lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 30 S R 7 W  
1/4  
S 22 | S 23  
1982

Reset the iron pipe alongside the iron post.

Note: The BTs described by Jelley as Ware BTs, appear to be those scribed by Johnstone. Ware found corner in 1975 per his survey map M 57-52. (V.Laugen, May 1996)