

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7241)

-----  
Set ¼ sec. post, from which  
A Pine 36" dia., bears N.43°W., 25 lks. dist.  
A Cedar 40" dia., bears N.80°E., 50 lks. dist.

Cor. fd. and used in GLO resurvey by Byars, Contract #450, dated July 28, 1882 - (DCSO records, Vol. 17 Page 7258)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, Jack Barnett, crew - Sept. 1964 - C.S. File 53/40-94

-----  
Found - Orig. 36" now 44" D.Fir, snag, N.43°W., 16.5 ft., recorded as Pine, shows good scar.  
Orig. 40" now 48" Cedar, snag, S.80°E., 33.0 ft., not healed over, ring count reveals approx. 50 yrs. before tree died, shows "¼S BT" scribe.  
This was recorded as N.80°E.

Set corner at intersection of dist. and brg. on NW. tree.  
Set brass cap at cor. mkd: County Surveyors Office

T 30 S R 7 W  
¼ S15 | S 14  
1964

New BTs -8" Cedar S.51°E., 11.8 ft. mkd. ¼ S15 CS BT.  
9" Cedar N.81°W., 11.9 ft. mkd. ¼ S14 CS BT.

Fd. corner as recorded by County in 1964 - BLM resurvey by John M. Jelley, Group #571, surveyed May/June 1965 - (DCSO records, Vol. 33 Pages 13861-62) **Added marks BLM 1965 to brass cap.**