

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7243)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.15°E., 26 lks. dist.
A Fir 30" dia., bears S.60°W., 6 lks. dist.

Douglas Co. Surveyors Office - Vernon R. Trace; Mike Darby; Jack Barnett, crew - Aug/Sept. 1964 - C.S. File 53/40-91

Found Squared post and BT stumps as follows:
36" D.Fir S.60°W., 4.0 ft. shows good scribe ¼ S11 and BT scar.
8" Fir, rotted remnants, N.15°E., 17.7 ft. Dug "BT" out.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W
¼ S 2
S 11
1964

New BTs:
12" D.Fir N.52°E., 25.6 ft. mkd. ¼ S2 CS BT.
9" Live Oak S.30°E., 15.5 ft. mkd. ¼ S11 CS BT.
This corner lies on N. slope approx. 150 ft. South of creek in bottom.

Fd. and Used in BLM resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson, Cadastral Surveyors - under Group #1456, surveyed Sept. 1988/Feb. 1989 - (DCSO records Vol. 50 Page(s) 19034-35)