

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7237)

Set ¼ sec. post, from which
A W.Oak 16" dia., bears S.28°E., 30 lks. dist.
A W.Oak 10" dia., bears S.25°W., 45 lks. dist.

Survey by R.H. Gee - For: Roseburg Lumber Co. - March 24, 1955 - C.S. File 41/385-3

Found White Oak BT.
Set 4" x 4" x 3 ft. Cedar post marked ¼ S11 on West face and ¼ S12 on East face, from which
A W.Oak 22", S.28°E., 19.8 ft. mkd. ¼ S12.
A Fir 14", S.25°W., 24.5 ft. mkd. ¼ S11 T30S R7W.
Metal tag placed on the Fir.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, Jack Barnett - Aug/Sept. 1964 - C.S. File 53/40-90

Found - 22" Oak snag S.28°E., 19.8 ft. opened and face rotted off.
14" Fir snag S.25°W., 24.5 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 7 W
¼ S11 | S12
1964
New BTs -25" Cedar N.43°W., 39.7 ft. mkd. ¼ S11 CS BT.
16" W.Oak N.51°E., 101.7 ft. mkd. ¼ S12 CS BT.

Mark F. Smalley - Roseburg Resources - Feb. 1995 - M 121 - 59

Found - 1964 County brass cap & Iron pipe
30" cedar, N.43°W. 39.7', healed.
16" oak, N.51°E. 101.7', center rotten.
18" oak, S.28°E. 19.8', face rotten original BT.
14" fir, S.25°W. 24.5', snag.
Scribed- 11" cedar, S.60°E. 13.6', "¼ S BT"
17" fir, S.29°W. 22.3', "¼ S BT"

Fd. and used in BLM resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson, Cadastral Surveyors - under Group #1456, surveyed Sept. 1988/Feb. 1989 - (DCSO records Vol. 50 Page(s) 19028-29)