

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7366-7)

Set a fir post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on North face; from which

A fir, 12" dia., bears N.52°E., 18 lks., mkd: 1/4 S BT.

A fir, 72" dia., bears S.45°W., 17 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - A. Boyer, C.S. - Witnesses: Joe Morgan, Howard Church, Lester Calder - Nov. 29, 1944 - Old Cor. Bk Pg. 155

Chained between SE corner & SW corner of section 6. Found remains of orig. post at 2658.3 ft. W of SE corner & from this point found a stump of an 84" Fir & rotten remains of a fir stump standing u about 18" above ground. The 84" Fir stump bore S.46°W., 12.3 ft. and the fir (15"±) N.52°E., 12.0' indicating that this must have been the corner & these trees the orig. BTs. The bark of the big stump was mutilated so much that any bark blazes would have been destroyed. The stump showed tree to be cut sometime n 1943 or 1944. Chained W 2832.9' to SW corner of section from this 1/4 corner. Ran north from 1/4 corner & fd a blaze on a fir on both N & S faces about 350 or 400 ft. North and cut in & found it to have been cut or marked about 57 years ago. Found another blaze about 250 ft. further North. Set a new BT

A 60" fir stump N.38°E., 27.3 ft. marked in wood 1/4 S6 CS BT (dist. to face of tree)

Used OBT for other BT S.46°W., 12.3 ft. remarked on wood of tree.

Set 6x6x8" S.S. rock for corner, cross on top.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - April 1965 - C.S. File 53/67-41

Found - 6"x"x8" S.S. with "X" on top at corner.

12" Fir, rotted stump, N.52°E., 12.0 ft. about 4" high, no scribe, probably remains of orig. BT.

72" now 84" fir stump S.46°W., 12.3 ft. shows "S7 1/4 S BT" rescribed by Boyer, stump is 7.0 ft. high.

60" Fir stump N.38°E., 27.3 ft. (to face) shows "1/4 S6 CS BT"

Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R8W 1/4 S 6
OFFICE 1965 S 7

New BTs- 10" W.Fir N.45°W., 3.4 ft. mkd: 1/4 S6 CS BT.

14" W.Fir S.4°E., 12.2 ft. mkd: 1/4 S7 CS BT.

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Mark Smalley - For: Roseburg Resources & Moore Mill - 8/2002
- M 137-50

Found - 1965 Douglas Co. Surveyors brass cap on an iron pipe
84" stump S.46°W., 12.3' (OBT)
60" stump N.38°E., 27.3' (OBT)
24" stump S.4°E., 12.2' healed
26" Fir N.45°W., 3.4' healed
Scribed- 40" W.Fir S.12°W., 44.9' "¼S BT"
15" W.Fir N.71°E., 13.7' "¼S BT"
12" W.Fir S.78°E., 56.8' "¼S BT"