

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 16 Page(s) 6612-13)

-----

Set a Dogwood post 4 ft. long, 4" triangular, 20" in the ground mkd. T29S R8W S32 on the N.; T30S R8W S5 on SE.; and S6 on SW. faces and 5 notches on the E. and 1 notch on the W. angles of the same, for the cor. to secs. 5 and 6, and from which

    A Hemlock 14" dia., bears N.21°E., 32 lks. dist. mkd. T29S R8W S32 BT.

    A Cedar 14" dia., bears S.15°E., 32 lks. dist. mkd. T30S R8W S5 BT.

    A Fir 36" dia., bears S.30°W., 38 lks. dist. mkd. T30S R8W S6 BT.

---

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-36

-----

Found - Orig. 14" now 26" Hemlock N.21°E., 21.1 ft., previously opened, face shows good scribing "S32 T29S R8W".

    Orig. 36" now 46" R.Fir S.30°W., 25.1 ft., shows good bark scribing.

    Remains of Cedar stump that checks bearing and distance for orig. SE. BT.

Set Brass cap at cor. mkd:           County Surveyors Office

S32	T 29 S	
S 6   S 5	T 30 S	R8W

1958

New BTs- 7" Hemlock bears S.26½°E., 33.1 ft. scribed T30S S5 R8W CC CS BT.

    4" Cedar bears S.11°W., 43.1 ft. scribed S6 CS BT.

---

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13878)

-----

The cor. of secs. 5 and 6 only, perpetuated and recorded by Byron in 1958, monumented with an iron post 1½" dia., firmly set, extending 8" above ground with brass cap mkd. in 1958, from which the remaining original bearing trees:

    A down Hemlock 26" dia., bears N.21°E., 32 lks. dist. mkd. T29S R8W S32 on an opened blaze.

    A Fir 46" dia., bears S.30°W., 40 lks. dist. mkd. to face, mkd. T30S R8W S6 BT on a bark blaze. (Rec. 38 lks.)

and bearing trees mkd. by Byron

(Cont. Next Page)

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only, (North)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A down Hemlock 8" dia., bears S.25°E., 47 lks. dist. mkd.  
T30S R8W CC S5 CS on partially healed double blaze.  
A Cedar 5" dia., bears S.10½°W., 66 lks. dist. mkd. S6 CS  
BT on an open blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,  
with brass cap mkd:

T 29 S R 8 W  
    S 32  
    S 6 | S 5  
T 30 S R 8 W  
    1965

from which a new bearing tree

A Fir 20" dia., bears S.64½°E., 66 lks. dist. mkd. T30S  
R8W S5 BT.

Reset the county iron post inverted alongside the iron  
post.

Cor. Fd. and used in BLM Resurvey by Dale T. Bedell and Bryan  
S. Seibold, Cadastral Surveyors - Under Group #1494, Surveyed  
July 1989/April 1993 - (DCS0 records Vol. 50 Page(s) 19019)

Mark Smalley - For: Roseburg Resources & Moore Mill - 8/2002  
- M 137-50

-----  
Found - 1965 BLM brass cap on an iron pipe  
11" Cedar S.9°W., 43.2' healed  
30" Fir S.64½°E., 43.6' healed  
Scribed- 8" Fir N.48°W., 5.8' "S32 BT"  
8" Fir N.13°E., 10.5' "S32 BT"