

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCS0 records Vol. 17 Page(s) 7345-6)

Set a fir post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on North face; from which
A fir, 6" dia., bears N.54°E., 18 lks., mkd: 1/4 S BT.
A fir, 5" dia., bears S.26°E., 17 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Donald R. Beck & C. Albert White, Cadastral Surveyor, under group #350 & 548, surveyed May 1963/July 1964 - (DCS0 records Vol. 32 Page(s) 13608-9)

The 1/4 sec. cor. of secs. 28 and 33, determined at record bearing and distance from the original BTs:
A fir, 8" dia., down and greatly decayed, bears N.54°E., 18 lks., no marks remain.
A fir, 9" dia., bears S.26°E., 17 lks. mkd. 1/4 S BT, on opened blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:
$$\frac{1}{4} \frac{S \ 28}{S \ 33}$$

T 30 S R 8 W
1963

from which new bearing trees
A fir, 16" dia., bears N.54°W., 107 lks., mkd: 1/4 S28 BT.
A fir, 20" dia., bears S.71°E., 104 lks., mkd: 1/4 S33 BT.

Douglas Co. Surveyors Office - John Powell & crew - 7/12/1968 - C.S. File 53/67-18

Found - 1963 BLM brass cap, properly marked.
16" D.Fir now 16" N.54°E., 70.6 ft. scribe visible "1/4 S28 BT"
20" now 20" D.Fir S.71°E., 68.6 ft., pitched over, scribing visible.
A road is to be built over 1/4 cor therefore set Witness corner
Orig. corner at road Sta. 141+03.96
Set brass cap at wit. cor. mkd: COUNTY SURVEYORS T30S R8W
Placed BLM BC OFFICE 1968 WC
by 1968 CS BC 60' EAST TO 1/4 $\frac{S \ 28}{S \ 33}$
New BTs- 10" hemlock N.81°W., 17.9 ft. mkd: WC 1/4 S28 CS BT.
15" D.Fir S.27°W., 25.2 ft. mkd: WC 1/4 S33 CS BT.

7/1973 Fd. Ok VRT, DCS0, C.S. 56/34-17

continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0906, surveyed July 2006/May 2007 - (DCSO recs Vol 56 Pg 22320 & Plat T30-8 2011)

The ¼ sec cor. of secs. 28 & 33 determined at record dist. from the remains of BTs mkd. by Beck & White in 1963-64

A decayed fir stump, 17" dia., bears S.75¼°E., 68.6 ft. with axe marks visible (Rec. S.71°E)

A sawed decayed fir stump, 40" dia., bears N.56½°W., 70.6 ft. with a healed blaze. (Rec. N.54°W.)

At the corner point

Set an iron post, 28" long, 2½" dia., 29" in the ground, with brass cap marked:

T30S R8W
¼ S 28
S 33
2006

from which new BTs

A fir, 10" dia., bears S.81°W., 37.3 ft., mkd: ¼ S33 BT.

A fir, 7" dia., bears N.4¾°W., 26.0 ft., mkd: ¼ S28 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

The geographic position (NAD 1983) of the 1/4 section corner of sections 26 and 33 was determined by a differentially corrected, mapping grade GPS receiver observation.

Latitude 42°55'30.7"N

Longitude 123°39'10.0"W.

(NAD 1983)

From this corner, a point established by Powell in 1968, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap mkd.

COUNTY SURVEYOR OFFICE T30S R8W WC 60' EAST TO S28 ¼ S33 1968 from which the remains of BTs mkd. by Powell

A tin-capped fir stump, 16" dia., bears S.27¾°W., 25.3 ft. with scribe marks C ¼ S33 visible on open blaze.

A decayed hemlock stump, size indeterminate, bears N.83½°W., 17.6 ft. with scribe mark B visible on open decayed blaze.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2972, surveyed May 2020/Feb2021 - (DCSO records Vol. 59 Page(s) 23960-1)

The ¼ sec. cor. of secs. 28 and 33, reported by Skeesick in 2006-07, monumented with an iron post, 2½" dia., firmly set, with top flush with the surface of the ground, with a brass cap (properly) mkd. Continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the BTs reported by Skeesick
A decayed fir stump, 17" dia., bears S.75¼°E., 68.6 ft.,
no marks visible.
A fir, 14" dia., bears S.81°W., 37.3 ft., with a healed
blaze.
A decayed fir stump, 40" dia., bears N.56½°W., 70.6 ft.,
no marks visible.
A fir, 11" dia., bears N.4¾°W., 26.0 ft., with a healed
blaze.
From this cor., a point established by Douglas County
Surveyor's Office, in 1968, reported by Skeesick in 2006-07,
bears N.89°25'03"W., 56.89 ft., monumented with an iron post,
1¼" dia., firmly set, projecting 12" above ground, with brass
cap mkd. COUNTY SURVEYORS OFFICE T30S R8W WC 60' EAST TO S28
¼ S33 1968, from which the remains of the bearing tree mkd.
by Douglas County Surveyor's office, reported by Skeesick
A tin-capped decayed fir stump, 16" dia., bears S.27¾°W.,
25.3 ft., with scribe marks C¼ S33 visible on open
blaze.
Corner is located W., 15 ft., of Union Creek Access Rd.,
graveled surface, 10 ft. wide, bears N.10°E. and S.10°W.