

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7352)

Set a cedar post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on North face; from which

 A fir, 13" dia., bears S.45°W., 22 lks., mkd: 1/4 S BT.

 A cedar, 8" dia., bears N.5°E., 12 lks., mkd: 1/4 S BT.

Reported as not fd, 4/8/1965 - DCSO, VRT - C.S. File 53/67-54

David Edwards - For: Moore Mill & Lumber Co. - Feb. 2013 - C.S. File 65/79-2

Set 1/4 Corner by proportion method

Set - 5/8"x30" steel rebar with 2 1/2" dia. Alum. Cap stamped per the 2009 BLM Manual and also stamped "LS 2339" and "2013".

 15" fir bears S.8°E., 24.8 ft

 24" fir bears S.82°W., 37.0 ft

 15" cedar bears N.47°W., 19.9 ft

 6 ft steel post 2 ft west.

1