

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7343-4)</p> <p>-----</p> <p>Set a cedar post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on West face; from which</p> <p> A cedar, 5" dia., bears N.74°E., 17 lks., mkd: 1/4 S BT.</p> <p> A fir, 44" dia., bears S.20°W., 43 lks., mkd: 1/4 S BT.</p>
<p>BLM dependent resurvey by Wayne L. Rogers, Lance J. Bishop, and James L. White, Cadastral Surveyors under Group No. 1240 surveyed Feb/July 1985 - (DCSO records Vol. 47 Page 18111)</p> <p>-----</p> <p>Point for the 1/4 sec. cor. of secs. 3 & 4, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 24" in the ground with brass cap marked:</p> <p style="text-align: center;">T30S R8W 1/4 S 4 S 3 1985</p> <p>from which</p> <p> A fir, 10" dia., bears S.33°E., 22 lks., mkd: 1/4 S3 BT.</p> <p> A fir, 7" dia., bears S.29°W., 9 lks., mkd: 1/4 S4 BT.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p>
<p>Gary Smithers - March 16, 2001 - C.S. File 65/37-2</p> <p>-----</p> <p>Found - 1985 BLM brass cap on iron pipe firmly set. 13" D.Fir at S.33°E., 22 lks. with healed face. 9" D.Fir at S.29°W., 9 lks. with healed face.</p> <p>New BTs- 8" D.Fir, S.64°E., 20.0 ft. to spike driven in side center, mkd. "1/4 S3 BT" with BT tag. 10" D.Fir, N.65°W., 15.7 ft. to spike driven in side center, mkd. "1/4 S4 BT" with BT tag.</p>