

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7329)  
-----  
Set a post 4 ft. long, 4" sq., 24" in the ground for the corner to Secs. 14, 15, 22, & 23, marked T30S R8W S14 on the NE, S23 on the SE, S22 on the SW and S15 on the NW faces with 3 notches on S and 2 notches on E edges, from which  
A fir, 24" dia. bears N.44°E., 44 lks mkd: T30S R8W S14 BT  
A fir, 28" dia. bears S.35°E., 23 lks mkd: T30S R8W S23 BT  
A fir, 10" dia. bears S.48°W., 38 lks mkd: T30S R8W S22 BT  
A fir, 22" dia. bears N.14°W., 42 lks mkd: T30S R8W S15 BT

BLM dependent resurvey by Donald R. Beck & C. Albert White, Cadastral Surveyor, under group #350 & 548, surveyed May 1963/July 1964 - (DCSO records Vol. 32 Page(s) 13598)  
-----  
The cor. of sees. 14, 15, 22, & 23, determined at record bearing and distance from the remains of the original BTs:  
A sawed fir stump, 38" dia., bears N.44°E., 44 lks., with T3 and other illegible scribe mks. on bark detached from stump.  
A fir, 45" dia., bears S.35°E., 23 lks., mkd. T30S R8W S23 BT on bark blaze.  
A rotted fir stump, size indeterminate, bears S.48°W., 38 lks., with no mks, remaining.  
A rotted fir stump, 28" dia., bears N.14°W., 42 lks., with no mks. remaining.  
At the corner point  
Set an iron post, 28" long, 24" dia., 24" in the ground, with brass cap mkd.  
T30S R8W  
S 15 | S 14  
S 22 | S 23  
1964  
from which new bearing trees  
A fir, 10" dia., bears N.80½°E., 117 lks., mkd. T30S R8W S14 BT.  
A fir, 20" dia. bears S.26°W., 83 lks mkd. T30S R8W S22 BT  
A fir, 8" dia. bears N.81½°W., 41 lks mkd. T30S R8W S15 BT

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Terrie Plouff - Feb. 4, 1981 - C.S. File 61/19-3  
-----  
Found - 1964 BLM brass cap on 2½" I.P. in good condition mkd T30S R8W S14 S15 S22 S23 1964.  
Orig. 38" burnt stump, no scribe marks visible bears N.44°E., 29.0 ft.  
Orig. BT, 45" Fir, burnt, no scribe marks visible bears S.35°E., 15.2 ft. continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

|       |       |             |       |
|-------|-------|-------------|-------|
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |

Orig. SW BT gone.  
Fd root fragments from orig. BT bears N.14°W., 27.7 ft.  
1964 BLM BT, 10" Fir stump with scribed T visible bears N.80½°E., 77.2 ft.  
1964 BLM BT, 22" Fir stump with well healed face bears S.26°W., 54.8 ft.  
1964 BLM BT, 8" now 9" Fir, dead & burnt with scribed T30S W S15 BT visible in single blaze, bears N.81½°W., 27.1 ft.  
New - 14" Fir bears N.81½°E., 148.7 ft. scribed T30S R8W S14 CS BT in double blaze.  
32" Fir bears S.57°E., 100.6 ft. scribed T30S R8W S23 CS BT in double blaze. (upper scribe is in blaze.)  
Boat spike in 18" Fir stump bears S.49°W., 42.5 ft.  
Boat spike in 36" Fir stump bears N.24°W., 58.0 ft.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 6/26/2014 - C.S. File 65/82-54  
-----  
Found - 1964 BLM Brass Cap.  
22" Fir stump S.22°W., 54.8'  
16" capped stump N.81½°E., 148.7' (Fir)  
45" capped Fir stump S.35°E., 15.2'  
Boat spike in 18" Fir Stump S.49°W., 42.5'  
Boat spike in 36" Fir stump N.24°W., 58.0'  
New - A 5" diam. Fir scribed "T30S R8W S14 BT" bears N.19°E., 8.7 ft.  
A six foot steel post is set 2 ft East  
Compass decl. 15½°E.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2972, surveyed May 2020/Feb2021 - (DCS0 records Vol. 59 Page(s) 23956-7)  
-----  
The cor. of secs. 14, 15, 22, & 23, reported by Beck and White in 1963-64; perpetuated by Douglas County Surveyor's Office, in 1981; subsequently perpetuated by Edwards, in 2014; monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd. from which the remains of the BTs reported by Beck and White  
A tin-capped fir stump, 38" dia., bears N.44°E., 29.0 ft., no marks visible. (Original)  
A tin-capped fir stump, 45" dia., bears S.35°E., 15.2 ft., no marks visible. (Original)  
A fir stump, 22" dia., bears S.26°W., 54.8 ft., with a healed blaze.  
Continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

and the remains of BTs mkd. by Douglas Co Surveyor's Office  
A tin-capped, decayed fir stump, 16" dia., bears N.81¼°E., 148.6 ft., with scribe marks T30S R8W S14 CS visible on open blaze.  
A tin-capped fir stump, 34" dia., bears S.57°E., 100.9 ft., with scribe marks T30S R8W S23 CS BT visible on bark.  
A decayed fir stump, 18" dia., bears S.48°W., 42.8 ft., no marks visible.  
A decayed fir stump, 34" dia., bears N.25¼°W., 59.0 ft., no marks visible.  
and a bearing tree mkd. by Edwards  
A fir, 7" dia., bears N.19°E., 8.7 ft., with a healed blaze.  
and new bearing trees  
A fir, 7" dia., bears S.55½°E., 23.5 ft., mkd. T30S R8W S23 BT.  
A fir, 14" dia., bears S.55½°W., 20.5 ft., mkd. T30S R8W S22 BT.  
A fir, 7" dia., bears N.24°W., 23.4 ft mkd T30S R8W S15 BT  
Corner is located W., 110 ft., of dirt road, 10 ft. wide, bears N.45°E. and S.45°W.  
NAD 1983 (2011)  
Latitude: 42°57'18.01" N. Longitude: 123°37'23.67" W.