

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs 13, 14, 23, & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7318)

Set a fir post 4 ft. long, 4" sq., 20" in the ground for the corner to Secs. 13, 14, 23, & 24, marked T30S R8W S13 on the NE face, S24 on the SE face S23 on the SW face and S14 on the NW face. Also 3 notch(es) on the S and 1 notch on the E angles of same, and from which
 A Live Oak, 11" dia., bears N.38°E., 13 lks., mkd: T30S R8W S13 BT.
 A Fir, 8" dia. bears S.52°E., 22 lks. mkd: T30S R8W S24 BT
 A Fir, 10" dia. bears S.20°W., 12 lks mkd: T30S R8W S23 BT
 A Fir, 10" dia. bears N.43°W., 13 lks mkd: T30S R8W S14 BT

Howard W. Johnstone - For: Roseburg Lumber Co. - May 28, 1962 - C.S. File 51/163-2

Found - 10" Fir S.20°W. 12 lks. (dying)
 10" Fir N.43°W. 13 lks. (dying)
 8" Fir S.52°E. 22 lks. (snag)
 11" Live Oak N.38°E. 11 lks.. (good)
Set - 1¼" by 24" Iron Pipe.
Scribed- 16" Cedar N.59°W. 29.4 ft.
 7" D.Fir S.74¼°W., 54.0 ft.
 12" Cedar S.59½°E. 31.0 ft.

Greg Lang - For: Roseburg Resources - 3/2006 - M150-3 & C.S. File 65/58-2A

Found - 1¼" iron pipe set by Johnstone from Orig evidence.
 A 15½" Cedar bears S.61½°E., 30.50 ft (1962)
 A 21" Fir bears S.17½°W., 8.0 feet (Orig)
 Found Johnstone's Fir to the Southwest but did not field locate it. (Record is S.74¼°W., 54.0 ft)
New - 6½" Fir bears N.82°E., 102.00 ft scribed "T30S R8W S13 BT"
 14½" Fir bears N.20½°W., 72.70 ft scribed "T30S R8W S14 BT"
Note - We set a spikes in the side and base of all bearing trees except the one existing tree mentioned above which was not field located. These were for measuring distances to the cor. Bearings to the trees were measured to the center with a total station & are based on the original 1882 Survey by W. H. Byars.
 Corner lies on a Westerly slope about 150' from the top of a ridge. It lies just above and not far from an old logging road to the South. Cont.

PRIMARY CORNER DESCRIPTION Cor Secs 13, 14, 23, & 24

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group No. 2139, surveyed July/Aug. 2006 (DCSO records Vol. 57 Page(s) 22540)

 The cor. of secs 13, 14, 23, & 24, perpetuated by Johnstone, in 1962, further perpetuated by Lang, in 2006, monumented with an iron pipe, 1½" dia., firmly set, projecting 12" above ground, with no cap, from which the remains of the original bearing trees

A live oak, 11" dia., bears N.38°E., 8.6 ft., with a healed blaze.

A fir, 21" dia., bears S.20°W., 7.9 ft., with a healed blaze.

A dead fir snag, 14" dia., bears N.43°W., 8.6 ft., with a healed blaze.

and bearing trees mkd. by Johnstone

A cedar, 15" dia. bears S.60¼°E. 30.5 ft with scribe marks 30S R8W S24 BT visible on a partially healed blaze

A fir, 18" dia., bears S.72½°W., 51.5 ft., with a healed blaze.

and bearing trees mkd. by Lang

A fir, 7" dia., bears N.82°E., 101.8 ft., with scribe marks T30S R8W S13 BT visible on open blaze.

A fir, 14" dia., bears N.20½°W., 72.5 ft., with scribe marks T30S R8W S14 BT visible on open blaze.

Cement a brass cap on top of the existing iron pipe, 3" dia., with 3½" stem, mkd.

T30S	R8W
S 14	S 13
S 23	S 24
2006	

Ron Quimby - Crew: J. Leonard & N. Fromdahl - 5/2014 - C.S. File 65/82-40

 Condition report

- Found - BLM Brass Cap
 11" Live Oak snag N.38°E., 8.6 ft. healed scar.
 9" D.Fir N.82°E., 101.8 ft. vis. scribe.
 18" cedar S.60°E., 30.5 ft. vis. scribe.
 24" fir S.72°W., 51.5 ft. healed scar.
 14" fir (snag) N.43°W., 8.6 ft. healed scar.
 18" fir N.20°W., 72.5 ft. vis. scribe.

Note - Cor. is on westerly slope approx. 150' west of ridge top and 50'± east of skid road.
 Compass decl. 15½°E.