

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7320)

-----

Set a fir post 4 ft. long, 4" sq., 20" in the ground for the corner to Secs. 11, 12, 13, & 14, marked T30S R8W S12 on the NE face, S13 on the SE face S14 on the SW face and S11 on the NW face. Also 4 notches on the South and 1 notch on the East angles of same, and from which

- A fir, 26" dia. bears N.44°E., 44 lks mkd: T30S R8W S12 BT
- A fir, 16" dia. bears S.28°E., 11 lks mkd: T30S R8W S13 BT
- A fir, 28" dia. bears S.60°W., 55 lks mkd: T30S R8W S14 BT
- A fir, 12" dia. bears N.32°W., 30 lks mkd: T30S R8W S11 BT

BLM dependent resurvey by Donald R. Beck & C. Albert White, Cadastral Surveyor, under group #350 & 548, surveyed May 1963/July 1964 - (DCSO records Vol. 32 Page(s) 13595-6)

-----

The cor. of secs. 11, 12, 13, & 14, determined from the remains of the original bearing trees:

- A sawed fir stump, 32" dia, bears N.44°E., 46 lks., no mks, remaining. (Record distance, 44 lks.)
- A sawed fir stump, 28" dia., bears S.18°E., 11 lks., no mks, visible on opened blaze. (Record bearing, S.28°E.)
- A sawed fir stump, 36" dia, bears S.60°W., 57 lks., no mks. remaining. (Record distance, 55 lks.)
- A down and rotted fir, 20" dia, bears N.32°W., 30 lks. with scribe marks S R8W and other illegible mks, visible.

At the corner point

Set an iron post, 28" long, 2½" dia, 21" in the ground, with brass cap mkd.

T30S	R8W
<u>S 11</u>	<u>S 12</u>
S 14	S 13
1964	

from which new bearing trees

- A fir, 11" dia, bears N.74¾°E., 188 lks., mkd. T30S R8W S12 BT.
- A pine, 6" dia., bears S.88½°E., 32 lks., mkd: T30S R8W S13 BT.
- A fir, 6" dia., bears S.67¾°W., 71 lks., mkd: T30S R8W S14 BT.
- A fir, 10" dia., bears N.22°W., 131 lks., mkd: T30S R8W S11 BT.

From this point an iron pipe, 1" dia., firmly set, 18" above ground, bears N.18°15'E., 1.22 chs.

continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group No. 2139, surveyed July/Aug. 2006 (DCSO records Vol. 57 Page(s) 22542-3)

-----

The cor. of secs. 11, 12, 13, and 14, monumented with an iron post, 2½" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A sawed fir stump, 36" dia., bears N.44°E., 30.4 ft., with no marks visible.

A sawed fir stump, 24" dia., bears S.18°E., 7.3 ft., with axe marks visible on a decayed blaze.

A sawed fir stump, 32" dia., bears S.62¾°W., 37.6 ft., with no marks visible. (Record, S.60°W.)

A decayed fir stump, size indeterminate, bears N.32°W., 19.8 ft., with no marks visible.

and bearing trees mkd. by Beck and White

A fir, 25" dia., bears N.74¾°E., 124.1 ft., with a healed blaze.

A pine, 12" dia., bears S.88½°E., 21.1 ft., with a healed blaze.

A fir, 16" dia., bears S.67¾°W., 46.9 ft., with a healed blaze.

A fir, 21" dia., bears N.22°W., 86.5 ft., with a healed blaze.

The geographic position (NAD 1983 (CORS 96)) of the corner of sections 11, 12, 13, and 14, was determined by a direct tie to a temporary point for which a position had been determined, to an accuracy level of less than 0.05 meter, 95% confidence level, relative to the NSRS stations noted above.

Latitude: 42°58'10.40"N Longitude: 123°36'15.46"W