

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7324-5)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. cor., from which
 A cedar, 14" dia., bears S.48°E., 20 lks., mkd: ¼ S BT.
 A fir, 18" dia., bears S.60°W., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - April 1965 - C.S. File 53/67-37

Found - Orig. 14", now 22" Cedar S.48°E. 13.2 ft., shows good scar. Didn't open.
 Orig. 18", now 31" D.Fir S.60°W. 9.2 ft., shows old "BT" bark scribe.
Set brass Cap at Cor. mkd: County Surveyor's Office, 1965
 T30S ¼ S2|S1 R8W
Remarked Orig. BTs: 22" Cedar S.48°E. 13.2 ft Mkd: ¼ S1 CS BT
 30" D.Fir S.60°W. 9.2 ft Mkd: ¼ S2 CS BT.
Note - This corner lies on very steep N.W. slope of ridge, Brass Cap is set in mound of stone.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 4/4/2013 - C.S. File 65/78-24

Found - 1965 DCS Brass Cap (properly mkd) in good condition. The Fir S.60°W. is a snag.
 Find a 25" dia. Cedar w/healed blazes S.45°E., 14.8'
New - An 8" dia. Fir scribed "T30S R8W S1 BT" bears N.45°E., 19.8'
 A 15" dia. Cedar scribed "T30S R8W S2 BT" bears South, 18.7'
 A 10" dia. Fir scribed "303 R8W 52 BT" bears S.29°W., 26.7'
 A six foot steel post is set 2' South
Compass decl. 16°E.