

PRIMARY CORNER DESCRIPTION 1/4 Cors Secs 12 & 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7321-2)

 Set a fir post 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. cor., marked ¼ S on N side & from which
 A fir, 12" dia., bears S.50°E., 25 lks., mkd: ¼ S BT.
 A fir, 14" dia., bears N.5°W., 29 lks., mkd: ¼ S BT.

BLM dependent resurvey by Donald R. Beck & C. Albert White, Cadastral Surveyor, under group #350 & 548, surveyed May 1963/July 1964 - (DCSO records Vol. 32 Page(s) 13594-5)

 The ¼ sec. cor. of secs. 12 and 13, monumented with an iron rod, 1/2" dia, firmly set, 6" above the ground, from which the remains of the original bearing trees:
 A sawed fir stump, 36" dia, bears N.8½°W., 29 lks., with a healed blaze. (Record bearing, N.5°W.)
 A sawed fir stump, 33" dia, bears S.41¼°E., 25 lks., with scribe mks. visible on opened blaze. (Record bearing, S.50°E.)
 and a local bearing tree
 A down hemlock, 10" dia, bears S.70½°E., 91 lks., mkd. S13 T30S R8W on opened blaze.
 At the corner point
 Set an iron post, 28" long, 2½" dia, 22" in the ground, with brass cap mkd.
 T30S R8W
 ¼ $\frac{S\ 12}{S\ 13}$
 1964
 from which new bearing trees
 A fir, 12" dia., bears N.53°E., 351 lks., mkd. ¼ S12 BT.
 A fir, 7" dia, bears S.56°E., 249 lks., mkd. ¼ S13 BT.
 Reset iron rod alongside the iron post.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor under Group No. 2139, surveyed July/Aug. 2006 (DCSO records Vol. 57 Page(s) 22544-5)

 The ¼ sec. cor. of secs 12 and 13, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground (with an iron rebar, 5/8" dia., projecting 2" above ground alongside), with brass cap (properly) mkd.
 from which the remains of the original bearing trees
 A decayed, sawed fir stump, 30" dia., bears S.41¼°E., 16.5 ft., with no marks visible.
 A decayed, sawed fir stump, 35" dia., bears N.8½°W., 19.1 ft., with a healed blaze.
 continued next page

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cors Secs 12 & 13

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and remains of a local BT reported by Beck and White
A decayed hemlock stump, size indeterminate, bears
S.70½°E., 60.1 ft., with no marks visible.
and bearing trees mkd. by Beck and White
A fir, 22" dia., bears N.53°E., 231.7 ft., with a healed
blaze.
A fir, 23" dia., bears S.56°E., 164.3 ft., with a healed
blaze.
and new bearing trees
A fir, 11" dia., bears S.3¼°W., 19.9 ft., mkd. ¼ S13 BT.
A fir, 14" dia., bears N.75½°W., 9.8 ft., mkd. ¼ S12 BT.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flauser and
Jeff Lorsung - 1/27/2025 - C.S. File 67/59-51

Found - BLM brass cap (Prop mkd) up 6"
Decayed sawn 30" fir stump S.41¾°E. 16.5'
Decayed sawn 35" fir stump N.8½°W. 19.1'
Decayed hemlock stump S.70½°E. 60.1'
26" fir N.53°E. 231.7' healed blaze
28" fir S.56°E. 164.3' healed blaze
13" fir S.3¼°W. 19.9'
17" fir N.75½°W. 9.8'

Notes - Compass decl. 14¼°E.
OGRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N. 49837.123 E. 94095.657