

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T30-10

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7379)

 Set post cor. secs. 30, 31, 25 and 36, from which
 A Cedar 36" dia., bears N.68°W., 15 lks. dist.
 A Cedar 15" dia., bears N.68°E., 31 lks. dist.
 A Cedar 40" dia., bears S.20°E., 16 lks. dist.
 A Cedar 15" dia., bears S.20°W., 33 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 17 Page(s) 7404-05)

 I find post cor. to secs. 25, 30, 31 and 36 lying upon the ground, greatly decayed with surveyors marks on it but cannot distinguish them. I find three witness trees and the stump of one about 10 ft. high.
 At cor. point, I set a stone 16x14x6 ins., 12" in the ground for cor. mkd. with 1 notch on S. and 5 notches on N. edges, from which
 A Cedar 15" dia., bears N.68°E., 31 lks. dist. mkd. T30S R9W S30 BT.
 A Cedar 40" dia., bears S.20°E., 16 lks. dist. mkd. T30S R9W S31 BT.
 A Cedar stub 15" dia. bears S.20°W., 33 lks. dist. mkd. t30S R10W S36 BT.
 In Sec. 36 I mark:
 A Cedar 18" dia., bears S.33¼°W., 145 lks. dist. mkd. T30S R10W S36 BT.
 A Cedar 36" dia., bears N.68°W., 15 lks. dist. mkd. T30S R10W S25 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1965 - C.S. File 53/53-28

 Found - 16x14x6 stone had been rolled down hill.
 15" Cedar now 24", N.68°E., 20.5 ft., open and found scribing.
 40" Cedar, down and burnt, S.20°E., 10.0 ft.
 18" Cedar now 26" S.33°W., 95.7 ft. This tree shows good scars.
 36" Cedar now 45" N.65°W., 9.9 ft., shows scars.

Set Brass cap at cor. mkd: County Surveyors Office

	T 30 S	
R10W	S 25 S 30	R9W
	S 36 S 31	
	1965	

(Cont. Next Page)

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T30-10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

New BTs- 24" Cedar N.68°E., 20.5 ft. scribed T30S R9W S30 CS
BT.
40" Fir S.50°E., 16.3 ft. scribed T30S R9W S31 CS
BT.

Survey by Mark Smalley - For: Roseburg Forest Products - Feb.
1994 - M 119-18

Found - 1965 DCSO Brass cap/iron pipe.
45" Cedar N.68°W., 9.9 ft., stump. Orig. BT.
24" Cedar N.68°E., 20.5 ft., stump, scribe visible.
Orig. BT.
40" Fir S.50°E., 16.3 ft., stump, scribe visible.
Scribed- 9" Fir N.56°E., 28.6 ft. "S30 BT"
7" Fir S.4°W., 10.7 ft. "S36 BT"
7" Fir S.55°W., 7.9 ft. "S36 BT"