

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T30-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page 7379)

Set ¼ sec. post, from which
A Cedar 10" dia., bears S.78°W., 35 lks. dist.
A Fir 36" dia., bears S.52°E., 14 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 17 Page 7407)

(35.15 chs.)
I find the ¼ sec. cor., a post 6 lks. East of my line, I destroy this post and also the marks on the two BTs.
(North, 40.0 chs.)
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Cedar 28" dia., bears N.62½°E., 46 lks. mkd. ¼ S BT.
A Fir 14" dia., bears N.35°W., 33 lks. mkd. ¼ S BT

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1965 - C.S. File 53/53-32

Found - 28" Cedar stump N.62½°E., 30.4 ft., scribe visible "S 4".
14" D.Fir now 24" N.35°W., 21.8 ft., shows scar.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S
¼ R10W S24 | S19 R9W
1965
New BTs- 50" D.Fir S.19°E., 26.0 ft. scribed ¼ S19 CS BT.
24" D.Fir N.35°W., 22.5 ft. scribed ¼ S24 CS BT.

DCSO-GIS Corner visitation - 5/24/2005 - Typed: 2/9/2011 - C.S. File 67/33-1

Monument - 1.25" IP/BC
Comment - ok

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 4/1/2015 - C.S. File 65/87-63

Found - 2½" brass cap on a 1" O.D. iron pipe, 1.1' tall, in good condition and fairly solid in the ground, leaning slightly to the South. Cap is oriented N.42°E. We set a Cedar post 3' North & paint the top in blue. Lat & long per Gamin hand held = 42°56'46.8" & 123°49'16.16" continued next pg

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T30-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

1893: 24" W.Cedar stump, N.62°30'E., 31.02' to heart center. We find a possible chopped out face. We paint the face in blue. FAIR COND.

1893: 31" D.Fir, N.32°W. 21.60' to left side center. We find a healed blaze and axe marks up high. We paint the face, the axe marks and a band around the tree in blue and add a new yellow tag. GOOD COND.

1965: 42" D.Fir high stump, 7' tall, S.16°30'E., 25.11' to right side center. We find a healed blaze and a 1965 BLM tag. We paint the face and a band around the stump in blue. GOOD CONDITION

New - 15" D.Fir with a dead top, N.45°30'E., 29.93' to a nail at right side center. We blaze and scribe "¼ S19 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag.

12" Hemlock, S.55°W., 21.18' to a nail at right side center. We bark scribe "¼ S24 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos County tag.

Decl. 17°