TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7446)

Set a Cedar post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which
A W.Fir, 10" dia., bears S.1°E., 19½ lks., mkd: ¼ S BT.
A cedar, 20" dia., bears N.37½°E., 17½ lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - J. Brady & F. Jones - Nov. 1965 - C.S. File 53/53-18

Found - Iron Pine at Corner (unrecorded)
20" Cedar Stump N.37½°E. 11.5 ft. scribed "¼S".
10" W. Fir Stump S.1°E. 12.8 ft., stump completely rotten.
Set brass Cap at Cor. Mkd: Co. Surveyors Office, 1965 ¼ S 18 / S 19
New BTs- 6" Cedar N.22°E., 12.7 ft. scribed ¼ S18 CS BT.
5" Laurel S.3°E. 21.4 ft. scribed ¼ S19 CS BT.
This corner is located about 150.0 ft. from top of ridge, on the west slope.

Fd. OK by B. Shaner, 2/1974 - M49-54