TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7437)

Set a stone 16x16x8", 12" in the ground for cor. of secs. 29, 30, 31, & 32 mkd with 1 notch on S & 5 notches on E edges, from which

A hemlock, 16" dia., bears N.77¾°E., 50½ lks., mkd: T30S R9W S29 BT.
A cedar, 18" dia., bears S.79½°E., 44 lks., mkd: T30S R9W S32 BT.
A cedar, 6" dia., bears S.32½°W., 7 lks., mkd: T30S R9W S31 BT.
A cedar, 14" dia., bears N.19¼°W., 38 lks., mkd: T30S R9W S30 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - Oct. 1965 - C.S. File 53/53-12

Found - Broken Stone at sec. corner.
16" Hemlock N.77¾°E., 50½ lks., rotten stump.
6" cedar, now 16" S.32½°W., 7 lks., open & find scribe "30S"
18" cedar, now 34" S.79½°E., 44 lks., shows good scar.
14" cedar, now 23" N.19¼°W. 38 lks. shows good scar.

Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R9W S30|S29
OFFICE 1965 S31|S32

New BTs- 17" cedar S.73°W., 4.4 ft scribed T30S R9W S31 CS BT
42" hemlock N.72°E., 50.0 ft. scribed T30S R9W S29 CS BT.

Fd. Ok by M. Smalley - 2/1994 - M119-18