

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T29-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7375-76)

-
- Set post cor. secs. 5, 6, 31 and 32, from which
- A Fir 50" dia., bears S.60°E., 65 lks. dist.
 - A Fir 30" dia., bears N.18°E., 57 lks. dist.
 - A Fir 15" dia., bears N.70°W., 50 lks. dist.
 - A Fir 12" dia., bears S.72°W., 60 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 17 Page(s) 7453)

The Sec. cor. has been destroyed by fire. I find 1 witness tree, which is mkd. on the bark. The other trees are burned. At cor. point, I set a stone, 16x12x8 ins., 12" in the ground for cor. to secs. 5, 6, 31 and 32, mkd. with 5 notches on E. and 1 notch on W. edges, from which

- A Fir 15" dia., bears N.70°W., 50 lks. dist., mkd. T29S R9W S31 BT. This is the only original witness tree sanding and it is dead.

I therefore mark 4 new witness trees as follows:

- A Fir 48" dia., bears N.80°E., 102 lks. dist. mkd. T29S R9W S32 BT.
- A Fir 48" dia., bears S.29 3/4°E., 54½ lks. dist. mkd. T30S R9W S5 BT.
- A Fir 48" dia., bears S.60°W., 79 lks. dist. mkd. T30S R9W S6 BT.
- A Fir 48" dia., bears N.38½°W., 42 lks. dist. mkd. T29S R9W S31 BT.

95 lks. West of this cor., I find a Fir 20" dia., on blazed line marked with 2 notches on E. and W. sides.

GLO resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 31 Page(s) 13012)

Post gone. Witness trees all standing and agree with notes furnished by the Surveyor General. Re-establish corner from the witness trees by setting a basalt stone 14 x 12 x 6 ins., 10" in the ground and marked with five notches on E. and 1 notch on W. edges.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T29-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #477 - Surveyed July 1962 - (DCSO records Vol. 31 Page(s) 13178-79)

The Sec. Cor., monumented with the basalt stone 16x12x8 ins., firmly set 12" in the ground by Porter in 1907, mkd. with 5 notches on the E.; and 1 on the W. edge, from which the 1893 bearing trees:

- A Fir snag 40" dia., bears N.80°E., 102 lks. dist., with scribe mark B visible on burned blaze.
- A rotted Fir snag, 43" dia., bears S.34 3/4°E., 49½ lks. dist., with no marks remaining. (Rec. brg. & dist., S.29 3/4°E., 54½ lks.)
- A Fir 47" dia., bears S.60°W., 76 lks. dist., with scribe marks T3 R9 S6 visible on burned blaze. (Rec. dist. 79 lks.)
- A Fir snag 45" dia., bears N.38½°W., 42 lks. dist., with no marks remaining.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29 S R 9 W
S 31 S 32
S 6 S 5
T 30 S
1962

from which new bearing trees:

- A Fir 18" dia., bears N.80°E., 32 lks. dist. mkd. T29S R9W S32 BT.
- A Fir 8" dia., bears S.24½°E., 12 lks. dist. mkd. T30S R9W S5 BT.
- A Fir 7" dia., bears S.64¼°W., 34½ lks. dist. mkd. T30S R9W S6 BT.
- A Fir 8" dia., bears N.34°W., 14 lks. dist. mkd. T29S R9W S31 BT.

Deposit the corner stone alongside the iron post.

Fd. and Used in BLM resurvey by Jack Bowder; John Farnsworth; Wayne Rogers, Cadastral Surveyors, under Group #1000, Surveyed May 1979/Sept. 1982 - (DCSO records Vol. 44 Page(s) 17076-77)