

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & S. 32, T29-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

ON THE DOUGLAS CO. AND COOS CO. LINE. SEE COOS CO.
SURVEYORS OFFICE FOR POSSIBLY MORE INFORMATION

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract
#57, dated April 12, 1855 - (DCSO records Vol. 17 Page 7375)

Set ¼ sec. post, from which
A Fir 24" dia., bears S.27°E., 20 lks. dist.
A Hemlock 18" dia., bears N.50°E., 50 lks. dist.

GLO resurvey by William M. Porter, Deputy Surveyor, Under
Special Instructions dated June 5, 1907, Independent of, but
in connection with his contract #768, dated March 8, 1907 -
(DCSO records Vol. 31 Page(s) 13012)

The ¼ sec. cor. which is a basalt stone 8 x 6 x 4 above
ground firmly set, marked; ¼ for the ¼ sec. cor., but not
agreeing with the notes furnished by the Surveyor General.
Witness trees standing and agree with notes furnished by the
surveyor general.

BLM remonumentation of certain orig. corner points by Jack W.
Bowder, Cadastral Surveyor under special instructions dated
May 3, 1957, surveyed Nov. 1977/March 1978

The ¼ sec. cor. of secs. 5 and 32,, on the S. bdy. of the
Tp., monumented with a sandstone, 12x12x8", firmly set 6" in
the ground, mkd. ¼ on N, face, from which the remains of an
original bearing tree:

A sawed fir stump, 50" dia., bears S.27°E., 20 lks., with
scribe marks BT visible on opened blaze

At the corner point

Set an iron post, 28", long, 2½" dia., 24" in the ground,
with brass cap mkd.

T29SR9W
¼ S32
S 5
T30S
1978

from which new bearing trees

A hemlock, 14" dia. bears N.24½°E., 65½ lks. mkd, ¼ S32 BT

A hemlock, 25" dia., bears S.18°E., 51 lks. mkd. ¼ S5 BT.

Deposit corner stone alongside iron posts

Corner is located 1.50 chs. E. of creek, 4 lks, wide, course
SW.

continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Burt Hult - For: Sun Studs INC - May 1984 (Filed with Douglas Co. Sept. 1992 & typed 3/2015) - M115-50

Found - 3" alum cap (properly) mkd. orig. stone is alongside of cap.
19" Hem. bears N.24°45'E., 43.2' scribes visible.
45" Fir stump bears S.27°E., 13.0' scribe visible.
34" Hem. bears S.18°E., 33.7', scribes visible.
Corner lies at timber corner and 85' East of stream brs. S.45°W.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - Feb. 10, 2015 - C.S. File 65/87-34

Found - 3¼" brass cap on a 2½" iron pipe, 0.3' tall, in good condition and solid in the ground. We find a sandstone rock with a "X" on the top, 0.4' south. This rock was fd per (rec.). There is a steel fence post 0.9' north. Note: there is a new slide area with 2 large stumps directly above BCIP at approx. 250'. 1978
44" D.Fir stump, S.27°30'E., 13.25' to face, 14.43' to heart center. Stump has a chopped out face with scribes visible and BLM tag in place. We paint the face in blue. 1855. Fair condition.
38" Hemlock, S.17°E., 33.58' to right side center. We find a healed blaze and a BLM tag in place. We paint the face and a band around the tree in blue. 1978. Good Condition.
22" Hemlock, N.25°E., 42.78' to right side center. We find a healed blaze and a BLM tag in place. We paint the face and a band around the tree in blue. 1978. Good Condition.
New BT - 40" Hemlock, S.60°W., 13.80' to a nail at left side center. We bark scribe "¼ S5 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos Co. tag.
Declination 17°E

BLM dependent resurvey by Randolph E. Younis, Cadastral Surveyor, under Group No. 2849 - surveyed Sept. 2016/March 2017 - (DCSO Records Vol. 59 Page(s) 23624-5)

The ¼ sec. cor. of secs. 5 & 32, on the N. bdy. of the Tp., perpetuated by Dado, in 2015; monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd. Continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & S. 32, T29-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which the remains of an original bearing tree
A fir stump, 44" dia., bears S.27°E., 13.2 ft., with
scribe marks BT visible on open blaze.
and the bearing trees mkd. by Bowder in 1978
A hemlock, 22" dia., bears N.23°E., 42.9 ft., with a
healed blaze. (Record, N.24½°E., 43.2 ft.)
A hemlock, 38" dia., bears S.18°E., 33.7 ft., with a
healed blaze.
and a bearing tree mkd. by Dado
A hemlock, 40" dia., bears S.58½°W., 13.9 ft., with scribe
marks ¼ S5 BT visible on bark and a spike in left side
center.
The original sandstone, 10x9", firmly set, projecting 5"
above ground, with an X on top, is alongside the cor.