

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7427)

A fir, 30" dia., which I mark ¼ S on W side, for ¼ sec. cor., from which
 A W.Fir, 30" dia., bears S.52°E., 50 lks., mkd: ¼ S BT.
 A fir, 12" dia., bears S.51½°W., 93 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - Oct. 1964 - C.S. File 53/53-47

Found - Both Orig. BTs & corner Tree called for:
 30", now 40" fir for corner, shows good scar on West side.
 30", now 44" W.Fir S.52°E. 33.0 ft., shows good soar.
 12" now 24" Fir S.51½°W. 61.4 ft., open & shows "¼S" scribe.
Set brass Cap 8.0 ft. S of Corner Tree for Wit. Corner & mkd: County Surveyor's Office, 1964 T30S R9W WC 8 ft. N ¼ S20|S21
New BTs- 8" D.Fir N.80°W. 15.9 ft. Mkd: W.C. ¼ S20 CS BT.
 24" Chinq. N.77°E. 45.5 ft. Mkd: W.C. ¼ S21 CS BT.
 30" Cedar Line Tree bears South 8.5 feet.

Gary Smither - For: Moore Mill Co. - 1/2001 - M136-54

Found 1964 county brass cap/iron pipe witness corner see 1964 renewal.
All trees are now stumps.
This is a young reproduction stand.
No new BTs taken.

BLM retracement by Aaron M Graham, Cadastral Surveyor, under Group No 2164, surveyed June/Oct. 2007 - (DCSO records Vol. 56 Page(s) 22256-8 and BLM Plat 2010-1 & 2010-2)

The ¼ sec. cor. of secs. 20 & 21, perpetuated by Tracy, in 1964; monumented with the remains of the original corner tree, a fir stump, 30" dia., with a healed blaze on the W. side, from which the remains of the original BTs
 A decayed fir stump, size indeterminate, bears S.49°E., 30.6 ft., no marks visible. (Record, S.52°E., 33.0 ft.)
 A fir stump, 25" dia., bears S.50¼°W., 58.7 ft., with scribe marks /4 S visible on open blaze. (Record, S.51½°W., 61.4 ft.)

continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the corner point
Saw the fir stump to ground level and drive on iron rod, 18" long, 3/4" dia., 16" into the center of the stump, with aluminum cap mkd.

T30S R9W

1/4
S 20 | S 21

2007

from which new BTs

A fir, 11" dia., bears S.52 1/4°E., 28.2 ft., mkd. 1/4 S21 BT.

A cedar, 13" dia., bears S.72°W., 14.0 ft., mkd. 1/4 S20 BT.

From the corner, the WC established by Tracy, bears S.3°41'16"E., 8.22 ft., monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.

from which remains of the bearing trees mkd. by Tracy

A chinquapin stob, size indeterminate, bears N.78°E., 42.9 ft., no marks visible.

A fir stump, 20" dia., bears N.81 1/4°W., 15.5 ft., no marks visible.