

PRIMARY CORNER DESCRIPTION Cor Secs 16, 17, 20, & 21

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7427)  
-----  
Set a stone 14x12x5", 10" in the ground for cor. of secs. 16, 17, 20, & 21 mkd with 3 notches on S & 4 notches on E edges, from which  
A fir, 8" dia., bears N.39¼°E., 65 lks., mkd: T30S R9W S16 BT.  
A fir, 30" dia., bears S.32¼°E., 77 lks., mkd: T30S R9W S21 BT.  
A cedar, 30" dia., bears S.37½°W., 29 lks., mkd: T30S R9W S20 BT.  
A fir, 48" dia., bears N.55°W., 24½ lks., mkd: T30S R9W S17 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - Oct. 1964 - C.S. File 53/53-46  
-----  
Found - Rock 5x10x12" for corner & 2 orig. BTs.  
30" now 36" cedar S.37½°W., 19.1 ft. open & shows scribe.  
48" now 54" D.Fir N.55°W., 16.1 ft. shows very good scar.  
No trace of other BTs.  
Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R9W S17|S16  
OFFICE 1964 S20|S21  
New BTs- 10" W.Fir S.80°E., 13.4 ft. mkd: T30S R9W S21 CS BT.  
8" W.Fir N.54°E., 16.9 ft. mkd: T30S R9W S16 CS BT.  
Note - We set rock between line tree and brass cap & built mound of rock.

Gary Smither - For: Moore Mill Co. - Jan. 2001 - M136-54  
-----  
Found - 1964 county brass cap/iron pipe per 1964 ren. stone is adjacent to corner.  
39" Cedar S.37½°W., 19.1 ft. scribe vis. w/tag.  
40" D.Fir snag N.55°W., 16.1 ft. w/healed face.  
13" W.Fir S.80°E., 13.4 ft. is a rotted stump w/healed face.  
8" W.Fir N.54°E., 16.9 ft. has fallen down.  
38" D.Fir snag S.28°E., 3.0 ft. w/scribe visible  
New BTs- 7" D.Fir N.84°W., 31.1 ft. to spike side center scribe "X" at breast height & "BT" at base w/alum tag.  
13" W.Fir N.17°E., 20.7 ft. to spike side center scribe T30 R9 S16 BT w/alum. tag.

PRIMARY CORNER DESCRIPTION Cor Secs 16, 17, 20, & 21

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

BLM retracement by Aaron M Graham, Cadastral Surveyor, under Group No 2164, surveyed June/Oct. 2007 - (DCSO records Vol. 56 Page(s) 22256-8 & BLM Plats 2010-1 & 2010-3)

-----  
The cor. of secs. 16, 17, 20, & 21, perpetuated by Tracy, in 1964, subsequently perpetuated by Smither, in 2001; monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of the original BTs

A cedar, 40" dia.. bears S.37½°W., 19.1 ft., with scribe marks 30 9 visible on partially healed blaze.

A decayed fir stump. size indeterminate, bears N.55°W., 16.2 ft., no marks visible.

and the remains of the BTs mkd. by Tracy

A roothole bears N.54°E., 16.9 ft., alongside of which is a down fir, 8" dia., with scribe marks T30S R9W S16 CS visible on partially healed blaze.

A fir stump, 9" dia., bears S.80½°E., 13.4 ft., with illegible scribe marks visible on partially healed blaze.

and the remains of a BT mkd by person(s) unknown

A fir snag, 38" dia., bears S.18°E., 3.1 ft., with scribe marks S20 BT 378 visible on partially healed blaze.

and the BTs mkd. by Smither

A fir, 15" dia., bears N.15¼°E., 20.6 ft., with scribe marks R9W S16 BT visible on partially healed blaze.

A fir, 9" dia., bears N.86°W., 31.4 ft., with a healed blaze.

and a new BT

A fir, 9" dia., bears S.64½°E., 28.2 ft., mkd. T30S R9W S21 BT.