

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5; 32 & 33, T29-9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7375)

Set post cor. of secs. 4, 5, 32 and 33, from which
A Hemlock 12" dia., bears S.74°E., 34 lks. dist.
A Hemlock 15" dia., bears N.74°W., 39 lks. dist.
A Fir 12" dia., bears N.74°E., 27 lks. dist.
A Fir 36" dia., bears S.38°W., 12 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 18 Page(s) 7435-36)

The post cor. to secs. 4, 5, 32 and 33 is lying upon the ground, considerably decayed, marked T29S S33 on NE.; R9W S4 on SE.; T30S S5 on SW.; and S32 on NW. faces, with 4 notches on E. and 2 notches on W. edges.
I find all the witness trees.
At cor. point, I set a hemlock post 4 ft. long, 4" sq., 24" in the ground for cor., marked T29S S33 on NE.; R9W S4 on SE.; T30S S5 on SW.; and S32 on NW. faces, with 4 notches on E. and 2 notches on W. edges, from which
A Fir 12" dia., bears N.74°E., 27 lks. dist. mkd. T29S R9W S33 BT. This tree is dead, in its stead, I mark:
A Fir 32" dia., bears N.63½°E., 58½ lks. dist. mkd. T29S R9W S33 BT.
A Hemlock 12" dia., bears S.74°E., 34 lks. dist. mkd. T30S R9W S4 BT.
A Fir 36" dia., bears S.38°W., 12 lks. dist. mkd. T30S R9W S5 BT.
A Hemlock 15" dia., bears N.74°W., 39 lks. dist. mkd. T29S R9W S43 BT.

GLO resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6632)

The Sec. Cor., which is a post firmly set, marked and witnessed as described by the Surveyor General.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Sept. 22, 1964 - C.S. File 53/53-71

Found - Orig. 12" now 20" Hemlock S.74°E., 22.4 ft., shows "9S" scribe in opened scar. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5; 32 & 33, T29-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Orig. 15" now 24" Hemlock, N.74°W., 25.7 ft., shows good scar.
Orig. 36" now 54" Fir stump S.38°W., 7.9 ft., shows face on top of stump.
No trace of NE. bearing tree.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S
S 32 | S 33
S 5 | S 4
T 30 S
1964
New BTs- 17" Hemlock N.12°E., 28.8 ft mkd. T29S R9W S33 CS BT
9" Hemlock S.22°W., 26.9 ft. mkd. T30S R9W S33 CS BT
Corner is on that portion of the county line between Coos and Douglas County that runs E & W on the North line of T30S R9W.

BLM resurvey by Harvey E. Wofford, Cadastral Surveyor, under Group #1023, surveyed July 1980 - (DCSO records Vol. 45 Page(s) 17274-75)

(Wofford, found 1964 brass cap, 3 Hathorn BTs; 1 Bushy BT and 2 Tracy BTs.) "No other suitable trees within limits."

From the point, United States Coast and Geodetic Survey triangulation station "CAMAS 2", bears N.23°09'E., 31.92 chs. dist., monumented with a concrete post, 8" sq. firmly set, projecting 4" above ground, with a standard brass tablet, 3½" dia., set in top, mkd. CAMAS 2 1942 and a triangle.

Fd. OK, April 1991 - M 113-20

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - Feb. 13, 2015 - C.S. File 65/87-35

Found - 2½" brass cap on a 1½" iron pipe, 0.8' tall, in good condition, somewhat loose in the ground, but will not pull out. We set a D.Fir limb post 3' north and paint the top in blue. 1964
19" Hemlock stub, S.72°E., 22.59' to right side center. We find an open face with scribes visible and a BLM tag in place. We paint the face in blue. 1855. Fair
56" D.Fir stump, S.45°W., 9.55' to heart center. We find a chopped out face with no visible works but a BLM tag in place. We paint the face in blue. 1855. Fair
continued next page

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

36" Hemlock stump, N.70°W., 26.31' to heart center. We find axe marks with scribes visible on reverse piece of wood and a BLM tag in place. We paint the face in blue. 1855. Poor condition.

30" D.Fir stump, N.62°30'E., 38.19' to heart center. We find an open face with scribes visible. We paint the face in blue. 1893. Poor Condition.

18" Hemlock, S.25°W., 25.45' to left side center. We find a healed blaze and a BLM tag in place. We paint the face and a band around the tree in blue. Tree leans to left and has some damage but overall. 1964. Good condition.

New BT - 28" D.Fir, N.32°30'W., 18.11' to a nail at left side center. We blaze and scribe "T29 R9 S32 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos Co. tag.

11" D.Fir, N.54°30'E., 10.46' to a nail at right side center. We blaze and scribe "T29 R9 S33 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos Co. tag.

20" D.Fir, S.73°E., 5.21' to a nail at left side center. We blaze and scribe "T30 R9 S4 BT". We paint the scribes and a band around the tree in blue and attach a yellow Coos Co. tag.

Declination 17°E

BLM Dependent resurvey by Joseph J Johnson, Cadastral Surveyor under Group #2864, surveyed Feb. 2017/Oct. 2018 - (DCSO Records Vol. 59 Page(s) 23692-3)

The cor. of secs. 4, 5, 32, & 33, perpetuated by Dado, 2015, monumented with an iron post, 1½" dia., firmly set, projecting 9" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

A hemlock snag, 19" dia., 8 ft. high, bears S.74°E., 22.4 ft., with scribe marks 9 S visible on partially healed blaze.

A decayed fir stump, 53" dia., bears S.38°W., 9.2 ft., with a healed blaze

A hemlock stump, size indeterminate, bears N.74°W., 27.1 ft., with reverse scribe marks BT visible on a detached wood fragment.

and the remains of a bearing tree mkd. by Bushey in 1893

A decayed fir stump, 32" dia., bears N.63½°E., 38.6 ft., with scribe marks R S33 visible on open blaze.

and a bearing tree mkd. by Tracy, Douglas County Deputy Surveyor in 1964, reported by Wofford in 1980

Continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T29-9

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

A hemlock, 19" dia., bears S.22°W., 26.4 ft., with a healed blaze.
and the bearing trees mkd. by Dado
A fir, 11" dia., bears N.52¾°E., 10.5 ft., with scribe marks T29 R9 S33 BT visible on partially healed blaze and a spike driven at the base on right side center.
A fir, 21" dia., bears S.76°E., 5.4 ft., with scribe marks T30 R9 S4 BT visible on partially healed blaze and a spike driven at the base on left side center.
A fir, 31" dia., bears N.33½°W., 18.2 ft., with scribe marks 29S R9W S32 BT visible on partially healed blaze and a spike driven at the base on left side center.

ON THE COUNTY LINE - CHECK WITH COOS COUNTY FOR POSSIBLY MORE INFORMATION