

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7375)

Set ¼ sec. post, from which
A Fir 18" dia., bears N.23°E., 31 lks. dist.
A Fir 15" dia., bears S.32°W., 40 lks. dist.

Douglas Co. Surveyors Office - Gary L. Langlitz; P. Earle, crew - Nov. 6, 1974 - C.S. File 57/12-3

Found - An orig. 18" D.Fir, now a 30" stump, bears N.23°E., 20.5 ft. We open and find good scribing "T".
An orig. 15" D.Fir, now a 36" stump, bears S.32°W., 27.8 ft. (Rec. S.32°W. 26.4 ft.) showing a good scar and faint scribe marks on the bark above the scar.

At the corner, WE SET a 1" x 30" I.P. with brass cap mkd.
County Surveyors Office 1974

T 29 S
1/4 S 33 R
S 4 9
T 30 S W

New BTs- 12" Hemlock bears N.77½°E., 16.3 ft. scribed ¼ S33 CS BT.

An 11" Port Orford Cedar, bears N.12°E., 14.2 ft. scribed ¼ S33 CS BT.

Fd. OK, April 1991 - M 113-20

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 2/25/2015 - C.S. File 65/87-51

Found - 1974 2½" brass cap on an 1¼" O.D. iron pipe, 0.4' tall, in good condition and solid in the ground.
We set a cedar post 3' north and paint the top in blue.

1855: 30" D.Fir stump, 3' tall, N.25°E., 20.35' to heart center. We find visible scribes in a sawed out face with a Douglas Co. tag in place. **We paint** the face and "BT" in blue. Fair condition.

1855: 36" D.Fir tall stump, 6' tall, S.33°W., 28.28' to right side center. We find visible scribes in a sawed out face with a Douglas Co. tag in place.
We chop an "X" into the stump and paint the face, the "X" and "BT" in blue. Fair

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

1974: 18" hemlock, N.78°E., 16.25' to right side center. We find a mostly healed blaze with a Douglas Co. tag in place. **We paint** the face and a band around the tree in blue. Good condition.

1974: 13" W. Cedar, N.12°30'E., 14.23' to right side center. We find a healed blaze with a Douglas Co. tag in place. **We paint** the face and a band around the tree in blue. Good condition.

New BTs- 12" D.Fir, S.76°W., 22.79' to a nail at left side center. We blaze and scribe "¼ S4 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos Co. tag.

12" D.Fir, N.47°30'W., 39.27' to a nail at left side center. We blaze and scribe "¼ S33 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos Co. tag.

dec 17°E

BLM Dependent resurvey by Joseph J Johnson, Cadastral Surveyor under Group #2864, surveyed Feb. 2017/Oct. 2018 - (DCSO Records Vol. 59 Page(s) 23691)

The ¼ sec. cor. of secs. 4 & 33, perpetuated by Langlitz, Douglas Co. Deputy Surveyor, in 1974, subsequently perpetuated by Dado, Feb. 2015, monumented with an iron post, 1½dia., firmly set, projecting 5 ins. above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

- A fir, 31" dia., bears N.23°E., 20.5 ft., with scribe marks BT visible on open blaze.
- A decayed fir stump, 39" dia., bears S.32°W., 28.2 ft., with illegible scribe marks visible on open blaze. (Record, 26.4 ft.)

and the bearing trees mkd. by Langlitz

- A cedar, 13" dia., bears N.10½°E., 14.1 ft., with a healed blaze.
- A hemlock, 18" dia., bears N.76½°E., 16.3 ft., with a healed blaze.

and the bearing trees mkd. by Dado

- A fir, 13" dia., bears S.62¼°W., 22.8 ft., with scribe marks ¼ S4 BT visible on open blaze and a spike driven at the base on right side center.
- A fir, 13" dia., bears N.49½°W., 39.2 ft., with scribe marks S33 BT visible on partially healed blaze and a spike driven at the base on left side center.

ON THE COUNTY LINE - CHECK WITH COOS COUNTY FOR POSSIBLY MORE INFORMATION