

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7395

Set post, cor. secs. 9, 10, 15, & 16, from which
A laurel, 5" dia., bears N.50°E. 10 lks.
A laurel, 8" dia., bears S.70°E. 22 lks.
A laurel, 6" dia., bears N.45°W. 18 lks.
A fir, 5" dia., bears S.50°W. 27 lks.

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7430-1)

The cor. to secs. 9, 10, 15, & 16 has been destroyed by fire, I find the witness trees. At cor. point I set a stone, 16x12x6" 12" in the ground for cor. to secs. 9, 10, 15, & 16, marked with 4 notches on S & 3 notches on E edges, from which
A laurel, 5" dia., bears N.50°E., 10 lks., mkd: T30S R9W S10 BT.
A laurel, 8" dia., bears S.70°E., 22 lks., mkd: T30S R9W S15 BT.
A fir, 5" dia. bears S.50°W., 27 lks. mkd: T30S R9W S16 BT
A laurel, 6" dia., bears N.45°W., 18 lks., mkd: T30S R9W S9 BT.
These witness trees have been killed by fire, I therefore make four new tress.
A fir, 12" dia., bears N.70¾°E., 44 lks., mkd: T30S R9W S10 BT.
A fir, 11" dia., bears S.72°E., 35¼ lks., mkd: T30S R9W S15 BT.
A fir, 9" dia. bears S.30°W., 27 lks. mkd: T30S R9W S16 BT
A fir, 6" dia. bears N.37¾°W., 5½ lks. mkd: T30S R9W S9 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - Aug. 1964 - C.S. File 53/53-58

Found - Sandstone with 3 notches on E side & "X" on top measuring 12x10x6" & following BTs of 1893 survey
11" fir now 18" S.72°E., 23.1 ft. chopped open & showing good "S".
12" Fir now 18' S.70¾°E., 29.0 ft. stump showing burlwood.
9" fir now 15" S.30°W., 17.8 ft. opened & showing "T30R9" scribe.
6" fir now 6" N.37¾°W., 3.4 ft. rotted fragments, fd. good "B".
Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R9W S 9|S10
CONT. Set rock beside cap, OFFICE 1964 S16|S15

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

New BTs- 13" D.Fir N.15°E., 18.0 ft. Mkd: T30S R9W S10 CS BT.
10" Cedar S.24°E., 21.3 ft. mkd: T30S R9W S15 CS BT.
19" D.Fir S.50°W., 3.5 ft. mkd: T30S R9W S16 CS BT.
10" D.Fir N.16°W., 22.6 ft. mkd: T30S R9W S9 CS BT.

State Hwy map File M-7 (9B-13-6) {Fd. 1964 BC} 6/1975

Howard W. Johnstone - For: Roseburg Lumber Co. - Aug. 1982 - M90-26

Found - 1964 County brass cap and iron pipe.
17" cedar, S.20°E., 21.9 ft. scribe visible.
21" fir, S.50°W., 3.5 ft. Down on face.

New BTs- 12" fir, N.68°E., 31.0 ft.
10" fir, N.21°W., 26.2 ft.
6" cedar, S.46°W., 11.1 ft.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2088, surveyed Aug. 2004/June 2005 - (DCSO records Vol. 54 Page(s) 21271-2)

The cor. of secs. 9, 10, 15, & 16, perpetuated by Tracy, in 1964, monumented with an iron post, 1" dia., firmly set, projecting 3" above ground, next to the rootwad of a down bearing tree, with brass cap (properly) mkd. from which the remains of an original bearing tree

A fir stump, 12" dia., bears S.50°W., 19.7 ft., with no scribe marks visible on partially healed blaze. (Record, 17.8 ft.)

and the remains of the bearing trees mkd. by Bushey

A fir stump, 18" dia., bears N.70¾°E., 29.0 ft., with remains of a healed blaze.

A roothole bears S.72°E., 23.3 ft., alongside of which is a down fir, size indeterminate, no marks visible.

A fir stump, 17" dia., bears S.30°W., 18.6 ft., with scribe marks 9 visible on partially healed blaze. (Record and to face, 17.8 ft.)

A roothole bears N.37¾°W., 3.6 ft., alongside of which is a down fir, 16" dia., with a healed blaze.

and the remains of the bearing trees mkd. by Tracy

A roothole bears N.15°E., 18.0 ft., alongside of which is a down fir, 15" dia., with a healed blaze.

A cedar, 22" dia., bears S.24¼°E., 21.7 ft., with a healed blaze.

A roothole bears N.16°W., 22.6 ft., alongside of which is a down fir stump, 10" dia., with axe marks, no blaze, and illegible reverse scribe marks visible on loose piece of wood. continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of the BTs mkd. by Johnstone, in 1982
A cedar, 7" dia., bears S.42¾°W., 11.0 ft., with scribe marks S16 BT visible on partially healed blaze and a nail in face with brass washer mkd. RLS 498.
A decayed fir stump, size indeterminate, bears N.21½°W., 26.1 ft., no marks visible.
and new bearing trees
A fir, 5" dia., bears N.65°E., 26.1 ft., mkd. X BT.
A cedar, 14" dia., bears N.85°W., 59.0 ft., mkd. T30S R9W S9 BT.

Fd. Ok by Carl Sweeden, 11/2007 - M154-67