

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7397

Set ¼ sec. post, from which
A fir, 8" dia., bears N.64°W. 10 lks.
A fir, 6" dia., bears N.46°W., 10 lks.

Ben B. Irving - Witnesses: LaVern Sutherlin, Herman Aydelot & T.L. Clinton Hyde - C.S. 37/115

Identified by old fir snag N.46°W., 10 lks. bearing scribe marks and stump (rotten) probably other 0BT. as it checks both bearing and distance.
Set 4" cedar post for corner and marked as new BTs:
A 28" fir S.36°10'W., 10.4 ft.
A 22" fir N.26°25'E., 11.8 ft.

Douglas Co. Surveyors Office - James W. Byron & crew - March 15, 1963 - C.S. File 49/100-79

Found - 4"x4" scribed post at corner & both BTs as recorded by BB Irving, 1927
28" now down Fir stump S.36°W., 10.4 ft.
22" now 24" Fir stump N.26°E., 11.8 ft. shows scribing.
Set brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963
¼ S4|S3
New BTs- 15" hemlock bears N.76°E. 28.0 ft scribed ¼ S3 CS BT
7" hemlock bears N.27°W., 42.1 ft scribed ¼ S4 CS BT
Note - Corner is 75 ft. North of road.

Ronald Stuntzner - For: BLM - 8/1980 - M85-17

The ¼ corner to secs. 3 & 4 was perpetuated in its orig. position by Ben Irving in 1927.
Found 1963 county BCIP marked "COUNTY SURVEYORS OFFICE ¼ S4|S3 T30S R9W 1963" from which
1927 BT 24" stump (DF) N.26°E., 11.8'; other 1927 BT missing;
10" fir stump/tag, no record N.19°E., 26.0'; 20" W.F. N.76°E., 28.0' (1963 Co. BT); 1963 Co. BT N.27°W., 42.1', is 10" WF; (Record last two BTs is Hem. species)

continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ken Hoffine, L.S. 2291 - For: Lone Rock Timber Co. - May 1994
- M 120-24

Found - County Surveyors Brass Cap, 1.5' above ground.
24" White Fir, bears N.75°57'E., 28.3'. Well healed
scar w/tag.
29" Douglas Fir stump, bears N.21°03'E., 27.1'. Well
healed scar w/tag, no rec.
19" White Fir, bears N.27°05'W., 41.8'.
24" rotted stump w/tag along side bears N.26°53'E.,
11.5'.

Corner lies on flat ground approx. 1 chain west of road & 1½
chains east of pond.

Fd. Ok by D.Edwards, 2/2005 - M147-17

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor,
& Robert H. Browning, Surveying Techn., under Group #1579,
surveyed Feb./April 1991 - (DCS0 records Vol. 50 Page 19236)

The ¼ sec. cor. of secs. 3 and 4, perpetuated by Irving, in
1927, from original evidence no longer in existence, and
further perpetuated by Byron, in 1963, monumented with an
iron post, 1¼" dia. firmly set in concrete, projecting 16"
above ground, with brass cap (properly) mkd.

from which the remains of a bearing tree mkd. by Irving

A fir stump, 22" dia., bears N.26°E., 17 lks., no marks
visible.

and bearing trees mkd. by Byron

A hemlock, 25" dia., bears N.76°E., 42 lks., with healed
blaze.

A hemlock, 18" dia., bears N.27°W., 63½ lks., with healed
blaze.