

PRIMARY CORNER DESCRIPTION Cor Secs 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7390

-----

Marked a fir, 5" dia., for cor. of secs. 22, 23, 26, & 27, from which

- A fir, 10" dia., bears S.89°E. 21 lks.
- A fir, 12" dia., bears N.60°W. 30 lks.
- A fir, 6" dia., bears S.5°W. 6 lks.
- A fir, 5" dia., bears N.31°E. 14 lks.

GLO survey by Wm. Bushey, Deputy Surveyor, contract 613, dated April 29, 1893 - (DCSO records Vol. 17 Page(s) 7413-4)

-----

Cor. to secs. 22, 23, 26 & 27 which is a Fir, 5" dia., mkd: T30S S23 ON NE, R9W S26 on SE, S27 on SW & S22 on NW faces with 2 notches on S & E edges, from which

- A fir, 5" dia., bears N.31°E., 14 lks., mkd: T30S R9W S23 BT.
- A fir, 10" dia., bears S.89°E., 21 lks., mkd: T30S R9W S26 BT.
- A fir, 6" dia., bears S.5°W., 6 lks., mkd: T30S R9W S27 BT.
- A fir, 12" dia., bears N.60°W., 30 lks., mkd: T30S R9W S22 BT.

The two last trees were marked in the bark. I mark them in the wood.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - Oct. 1964 - C.S. File 53/53-43

-----

Found - Orig. BTs. as follows:

- 6", now 15" D.Fir S.5°W. 4.0 ft., open & find "B" scribe.
- 10", now 24" D.Fir S.89°E. 13.9 ft., shows faint scar.

Set Brass Cap at Cor. mkd: County Surveyors T30S R9W S22|S23  
Office, 1964 S27|S26

Remarked Orig. BTs -

- 15" D.Fir S.5°W. 4.0 ft. Mkd: T30S R9W S27 CS BT
- 24" D.Fir S.89°E. 13.9 ft. Mkd: T30S R9W S26 CS BT

No other trees available This corner lies on steep, SW slope approx. 100.0 ft. above creek.

FD ok by D. Edwards - 2/2007 M152-35