TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7393

Set ¼ sec. post, from which
A cedar, 20" dia., bears N.5°W. 42 lks.
A cedar, 12" dia., bears South 50 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - S. Bilow - July 1958 - C.S. File 49/100-1

Found - Orig. 20", now 24" Cedar Snag N.5°W. 27.7 ft., exposed scribing ¼.
Also find root section of Cedar that checks bearing & distance for Orig. South BT.
Set Brass Cap at Corner mkd: ¼ S 2 / S 11 T30S R9W County Surveyors Office, 1958
New BTs- 20" Cedar bears N.46°W. 13.2 ft. scribed ¼ S2 CS BT
12" R.Fir bears S.10°E. 14.0 ft. scribed ¼ S11 CS BT

Fd. Ok 1/12/1974 B. Shaner M49-51

Tony Hostetter - For: Seneca Jones Timber Co. - 1/2007 M152-28

Found - Brass cap & BTs as described by Douglas Co. Surveyor in 1958 (except Cedar at N.46°W., is now a stump
New - 16" Cedar, scribed "S2 ¼ BT", bears N.11°E., 6.6 ft. to spike.
22" Fir scribed "S2 ¼ BT", bears N.56°E., 22.5 ft. to spike.
BT measurements are to the head of a 6" spike placed in the root collar below scribed face

Fd. as per M152-28 by D Edwards, 7/2016 - C.S. File 65/92-13