

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 57 dated April 12, 1855 - (DCSO Records Vol. 17 Page(s) 7389

Set ¼ sec. post, from which
 A fir, 8" dia., bears S.75°W. 15 lks.
 A hemlock, 8" dia., bears N.85°E. 11 lks.

Shaner Engineering - For: Moore Mill & Lumber, Bandon OR. - Jan. 12, 1974 - M49-51

Set - Brass cap mkd: T30S R9W WM ¼ S2, S1 1974
 24" Cedar stump scribed "¼ S2 BT" bears N.13°W. 66.7 ft
 36" D.Fir stump scribed "¼ S1 BT" bears S.18°E. 94.0 ft
Note- This corner is on a slide area & may move. The corner also lies on an old road. No orig. evidence fd.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - Sept. 18, 1997 - C.S. 64/78-4

Found - 2½" dia. Brass cap on a 1½" OD iron pipe protrudes 6" above ground BC/IP is plumb and firmly set.
 24" now 22" dia. 4' high Cedar stump, with visible scribing "¼ S2 BT", Note: this BT has slide out of position now, bears N.4°W., 64' (rec N.13°W., 66.7' 1974
 36" now 34" dia. 3' high rotted D.Fir stump, with scribing visible "¼ S1 BT", bears S.18°E., 94' (agrees with rec.) 1974
New - 6" D.Fir double blazed and scribed "¼ S2 CS BT", bears S.68°W., 5.7'
 15" D.fir double blazed and scribed "¼ S1 CS BT", bears S.59°E., 35'.
 8" D.Fir double blazed and scribed "¼ S2 CS BT", bears N.9°W., 12'.
 8" D.Fir double blazed and scribed "¼ S1 CS BT", bears S.15½°E., 24.5'.