

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7381)

-----  
Set ¼ sec. post, from which  
A Fir 10" dia., bears N.10°W., 5 lks. dist.  
A Fir 24" dia., bears S.85°E., 40 lks. dist.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1965 - C.S. File 53/53-34

-----  
Found - 10" D.Fir, down and rotten, N.10°W., 3.3 ft.  
24" D.Fir, down and rotten, S.85°E., 26.4 ft. Open tree for scribe, found "BT".

Set Brass cap at cor. mkd: County Surveyors Office  
T 30 S  
R9W  $\frac{S}{S}$   $\frac{36}{1}$   
T 31 S

New BTs- 8" Cedar N.13°E., 27.7 ft. scribed T30S R9W ¼ S36 CS BT.

5" D.Fir S.37°W., 72.0 ft. scribed S1 CS BT.

This corner is located in bottom of small ravine.

Kris DeGroot - For: Roseburg Resources - 6/2001 - M 137-13

-----  
Found - 1¼" IP by Powell, DCSO, in 1965, firmly set flush w/ground on a steep east slope, 10 ft. west of bottom of ravine w/¾" brass cap properly stamped.  
8" Cedar scribed "T30S R9W ¼ S36 CS BT" uprooted by felled trees and slid out of position into a ravine. No evidence of the orig. position.

9" D.Fir bears S.37°W., 71.5 ft. with healed double blaze. (Rec. S.37°W., 72.0 ft.)

New BT - 18" D.Fir bears N.83°30'W., 30.0 ft. scribed "¼ S36 BT"

Note- All new BTs have double blazed faces w/brass washer stamped "PLS 1941" nail into the lower blaze. Bearings are taken to the center of the tree at the root crown & distances are measured to a nail in the root crown at the center of the tree all BTs have a 6" red band painted around the tree & the blazed face painted red & BT signs nailed to the tree.