

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 12; & S 7, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7370)

-----  
Set ¼ sec. post, from which  
A Chinquapin 9" dia., bears S.60°W., 10 lks. dist.  
A Chinquapin 6" dia., bears S.65°E., 26 lks. dist.

BLM resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson, Cadastral Surveyors - under Group #1339, surveyed Aug/Nov. 1986 - (DCSO records Vol. 48 Page(s) 18357)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an stainless steel post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:  
T 30 S  
R 9 W R 8 W  
¼  
S 12 | S 7  
1986

from which  
A Fir 14" dia., bears N.60°E., 31½ lks. dist. mkd. ¼ S7 BT  
A Fir 12" dia., bears N.12°W., 8½ lks. dist. mkd. ¼ S12 BT  
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Resources - Nov. 1988 - M 101-44

-----  
CORNER REPORT ONLY  
Found - 1988 Cadastral brass cap/iron pipe mkd. ¼ S12 | S7  
10" Fir N.12°W., 5.6 ft. scribe visible.  
12" Fir N.60°E., 20.8 ft. scribe visible.  
(At the time of this report, the above BLM survey had not been put on file with the DCSO)

Troy Rambo - For: Roseburg Resources - May/July 2003- M142-69

-----  
Found - 13" DF with a healed face - bears N.12°W., 8½ lks.  
14" DF with a healed face - bears N.60°E., 31½ lks.  
Scribed- "¼ S12 BT" on an 11" DF - bears S.59°W., 3.4 ft.  
"¼ S7 BT" on an 8" DF - bears S.5°E., 13.1 ft.  
All new BTs were measured to a 6" spike at side center base.  
Bearing were measured with a hand compass with decl. of 17°E.

continued next page

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 12; & S. 7, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Daniel A Renton, Minister-Glaeser Surveying - August Karlsen & Crew - For: US Department of Interior, BLM Beetle Battle North-Task C -May 17, 2023 - M178-73 A-D

-----  
Found - 3¼" BLM brass cap (properly mkd) on pipe, 0.6 ft above ground from which:  
An aluminum post with BLM boundary sign bears North 6 ft.  
An aluminum post with BLM boundary sign bears South 6 ft.  
A 14" Fir bears S.54°W., 3.5 ft with healed blaze & BT sign (2003)  
A 17" Fir bears N.16°W., 5.9 ft with healed blaze & BT signs (1988)  
A 16" Fir bears N.54°E., 20.5 ft with healed blaze & BT signs (1986)  
A 9½" Fir bears S.6°E., 13.3 ft with healed blaze & BT signs (2003)

Set chaining nail at side center, BT signs on front and rear, and painted red band for existing BTs