

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 34 & 35 T30-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO dependent resurvey by Leonard Carter, Public Land Surveyor, under Group No. 175, surveyed Sept/Nov 1936 - (DCSO Vol. 46 Page(s) 17635-6)

 Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 2, 3, 34, & 35, with brass cap mkd

T30S	R1E
S 34	S 35
S 3	S 2
T31S	
1936	

from which

A fir, 32" dia., bears N.44°E., 152 lks., mkd: T30S R1E S35 BT.

A fir, 47" dia., bears S.39°E., 87 lks mkd: T31S R1E S2 BT

A fir, 38" dia. bears S.25½°W., 59 lks mkd: T31S R1E S3 BT

A fir, 40" dia. bears N.61°W., 75 lks mkd: T30S R1E S34 BT

Maurice E. Farr, LS 1181 USFS - Leonard Herzstein & Randy Lopez - Sept. 25, 1984 - C.S. File 62/15-7

Note - Did not find original iron post. The corner point, as determined from the record bearings and distances from all orig. BTs, falls in the center of a 4 ft. wide creek, which bears down N.35°W.

Found - A 32" D.Fir, N.44°E., 100.3 ft. with healed blaze.

A 47" D.Fir, S.39°E., 57.4 ft. with healed blaze.

A 38" D.Fir stump, S.25½°W., 38.9 ft. with healed blaze.

A 40" D.Fir, N.61°W., 49.5 ft. with healed blaze.

Set - At corner point I set a 5/8" dia. rebar, 12" long, driven 10" to bedrock. Also set a 6 ft. steel fence post, 2 ft. in the ground, N.52°E., 4.7 ft. as a guard post, with USFS sign #54-4 attached

Reference Monuments:

RM 1 - N.80°E., 12.0 ft., a 2¼" O.D. iron pipe with brass cap 30" long, set 28" in ground with 2 ft. dia. mound of stone to top. Cap mkd. "RM 1 T30S R1E S35 ↙ 12 ft. to cor. L.S. 1181 1984"

RM 2 - S.10°W., 10.0 ft., a 2¼" O.D. IP with brass cap, 30" long, set 26" in ground with 2 ft. dia. mound of stone to 4" from top of I.P. Cap mkd. "RM 2 T31 R1E S3 ↗ 10 ft. to cor. LS 1181 1984".

Note - Corner is in small creek, which bears down N.35°W., and is 100 ft. NE of USFS Rd. #2925-600.