

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7472-3

Set post, cor. secs. 19, 20, 29, & 30, from which
 A fir, 6" dia., bears S.4°E., 72 lks.
 A fir, 10" dia., bears S.2½°W., 76 lks.
 A fir, 10" dia., bears N.15°E., 36 lks.
 A fir, 10" dia., bears N.85°W., 62 lks.
Build stone mound.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7585-6)

The cor. of secs. 19, 20, 29, & 30 is a badly decayed fir post, with marks still legible.
In place of the decayed post
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 19, 20, 29, & 30, with brass cap mkd
 T31S R1W
 S 19 | S 20
 S 30 | S 29
 1923
from which
 A fir, 20" dia., bears N.15°E., 36 lks., mkd: T31S R1W S20
 BT. (Old BT)
 A fir, 18" dia., bears S.4°E., 72 lks., mkd: T31S R1W S29
 BT. (Old BT)
 A fir, 20" dia., bears S.2½°W., 76 lks., mkd: T31S R1W S30
 BT. (Old BT)
 A fir, 20" dia., bears N.85°W., 62 lks., mkd: T31S R1W S19
 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1968 - C.S. File 54/71-98

Found - GLO Brass Cap, properly marked in 1922.
 6" D.Fir, now stump, S.4°E., 47.5 ft., opened for scribe "BT".
 10" D.Fir now stump, S.2½°W. 50.2 ft shows good scar
 10" D.Fir now stump, N.15°E. 23.8 ft shows good scar
 No trace of N. W. Bearing Tree.
New BTs- 14" D.Fir S.60°W. 15.2 ft scribed T31S R1W S30 CS BT
 10" D.Fir N.75°W. 13.3 ft scribed T31S R1W S19 CS BT
 22" D.Fir S.31°E. 15.2 ft scribed T31S R1W S29 CS BT
 8" Maple N.46°E. 37.6 ft scribed T31S R1W S20 CS BT.