

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7477  
-----  
Set post, cor. secs. 5, 6, 7, & 8, from which  
A fir, 10" dia., bears N.71°W., 41 lks.  
A fir, 24" dia., bears S.69°W., 59 lks.  
A fir, 10" dia., bears N.78°E., 10 lks.  
A fir, 10" dia., bears S.56°E., 26 lks.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - June 1966 - C.S. File 54/28-4  
-----  
Found - 10" D.Fir, now stump, N.71°W., 27.1 ft., had been opened for scribe.  
24" D.Fir, now stump, S.69°W., 38.9 ft., shows good scar.  
10" Fir, now burnt stub, S.56°E., 17.2 ft.  
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T31S R1W  
OFFICE S 6 | S 5  
1968 S 7 | S 8  
New BTs- 9" Maple S.16°W., 62.8 ft scribed T31S R1W S7 CS BT.  
10" Maple N.86°W. 68.0 ft scribed T31S R1W S6 CS BT.  
8" Hemlock S.84°E., 106.5 ft scribed T31S R1W S8 CS BT.  
8" Hemlock N.1°E., 109.3 ft scribed T31S R1W S5 CS BT.

Wm. Ruppert - For: USFS - Nov. 1977 - M65-50  
-----  
Found - 1966 County Surveyors brass cap on a 1" IP, properly marked.  
23" D.Fir stump N.70°W., 27.7 ft. scribe visible.  
41" D.Fir stump S.71°W., 40.4 ft. good scar.  
Rotted stump, S.59°E., 17.1 ft. no scribe visible.  
14" Maple, S.17°W., 61.7 ft. scribe visible  
12 Hemlock, S.83°E., 105.9 ft. scribe visible.  
8" fallen Hemlock, N.3°E., 106.2 ft. scribe visible.  
10" Maple snag, N.84°W., 67.6 ft. scribe visible.  
Scribed- 12" Hemlock, N.31°11'E., 187.2 ft. "T31S R1W S5 BT".  
26" D.Fir, N.09°34'W., 155.5 ft. "T31S R1W S6 BT".

continued next page

1

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Leonard E. Herzstein, LS USFS, under Group No. 2013, surveyed May 2002/Feb. 2003 - (DCSO records Vol. 54 page(s) 20785-6

-----

The cor. of secs. 5, 6, 7, & 8, perpetuated by the Douglas Co Surveyors Office in 1966, & perpetuated by Ruppert, in 1977; monumented with a 1½" dia. iron post, firmly set, projecting 20" above the ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A D.Fir stump, 36" dia., bears S.70¾°W., 40.0 ft., with healed blaze. (Record, S.69°W., 38.9 ft.)

A D.Fir stump, 24" dia., bears N.71°W., 27.7 ft., with scribe marks T3 R1W S6 visible on previously opened blaze. (Record and dist. to face 27.1 ft.)

and remaining BTs mkd. by County Surveyor in 1966

A W.Fir, 22" dia., bears S.83°E., 105.9 ft., with healed double blaze.

A maple, 17" dia., bears S.17°W., 61.7 ft., with healed double blaze.

A roothole, bears N.84°W., 67.6 ft., with decayed maple log alongside, no marks visible.

and bearing trees mkd. by Ruppert in 1977

A W.Fir, 20" dia., bears N.31¼°E., 187.2 ft., with healed double blaze.

A D.Fir, 32" dia., bears N.9¾°W., 155.5 ft., with fragmentary scribe marks visible on partially healed blaze.